1997 MOTOR MAGAZINE INDEX

HOW TO USE THIS INDEX

General subjects are listed first, with a month and page reference (if applicable), followed by related subjects and their references. The reference gives the month of the magazine in which a topic appeared, followed by a colon and the page or pages. For example, under the general subject of "Environmental Protection Agency (EPA)," the subtopic "sham refrigerant retrofits" was covered in the June issue on page 48, and is indexed as "Jun:48."

Regarding numbers (for example, years, model numbers, engine sizes, etc.), they are arranged in increasing order, without regard to alphabetization. Thus, years are listed with the earliest year first. Likewise, "BMW 3-series" would appear before "BMW 5-series," and "Audi 200" would be listed before "Audi 5000."

A

4Runner (Toyota), 2.4-liter, clutch chatter, Jun:61
80 (Audi), Quattro, 2.3-liter, engine warning light illuminates ('89), Aug:61
90 (Audi)
  groaning noise when turning left ('92-'94), May:116
  no blower motor ('93-'94), Nov:97
90/90 Quattro (Audi), 2.3-liter, engine warning light illuminates ('89), Aug:61
100 (Audi)
  2.3-liter, rough idle and stall ('90), Feb:50
  power loss/hard starting ('89), Oct:35
200 (Audi), power loss/hard starting ('89), Oct:35
200/200 Quattro (Audi), 2.2-liter, hard cold start ('89-'90), Oct:30
200SX (Nissan), expanded line of remanufactured transmissions, Jun:64
240 (Volvo)
  a/c retrofit kit, Jun:64
  brake noise, Jun:57-58
240SX (Nissan), transmission slippage (prior to 5/91), Mar:70, 73
300 (Mercedes-Benz)
  SD/SE
    brake pedal pulsation, Mar:70, 73, Oct:35
    parasitic key-off drain, May:113-114
300ZX (Nissan)
  2+2, detonation ('90), Feb:52
  belt squeal, oil leak ('90), Jul:65
  front brake clunk in reverse ('90), Jun:1
  transmission slippage (prior to 5/91), Mar:70, 73
  turbo
    clutch slippage, Jun:39
    detonation ('90), Feb:52
318i (BMW)
  electrical problems ('93), Nov:97
  rough idle with MIL lit ('90), Jan:47
323 (Mazda), 3.6-liter, stalls after start when cold ('88-'89), Jan:48
325i (BMW), electrical problems ('93), Nov:97
400SE (Mercedes-Benz)
  brake pedal pulsation, Oct:35
  parasitic key-off drain, May:113-114
405 (Peugeot)
  1.9-liter, coolant leak ('89-'91), Dec:58
  DL/S, intermittent stalling ('89), Aug:64
  no start ('89), Nov:94
500 (Mercedes-Benz)
  SEC/SEL
    brake pedal pulsation, Oct:35
    parasitic key-off drain, May:113-114
525 (BMW), rough idle ('93), Dec:57
525i (BMW), corroded fusible link ('90), Oct:30
530 (BMW), rough idle ('93), Dec:57
530i (BMW), loose oil pump cover (March '94), Mar:74
535i (BMW)
  1.1/1.3-liter, hard start/weak performance ('89), Feb:50
  stability control simulates misfire ('91-'92), Jul:63
540 (BMW), rough idle ('93), Dec:57
600 (Mercedes-Benz)
  SEC/SEL
    brake pedal pulsation, Oct:35
    parasitic key-off drain, May:113-114
626 (Mazda)
  3.6-liter, stalls after start when cold ('88-'89), Jan:48
  1998 tech report, Dec:26
  idle hunting ('89), Aug:62
635CSi (BMW), 1.1/1.3-liter, hard start/weak performance ('89), Feb:50
735i (BMW)
  1.1/1.3-liter, hard start/weak performance ('89), Feb:50
  stability control simulates misfire ('91-'92), Jul:63
740 (BMW), rough idle ('93), Dec:57
740 (Volvo)
  2.3-liter, squeaks and rattles ('89-'90), Dec:58
  a/c retrofit kit, Jun:64
  high a/c system pressure ('89), Oct:28
740i (BMW), loose oil pump cover (March '94), Mar:74
750 (BMW), rough idle ('93), Dec:57
750i (BMW), noisy rear brakes ('90), May:1
750iL (BMW), stability control simulates misfire ('89-'90), Jul:63
760 (Volvo)
  2.3-liter, squeaks and rattles ('89-'90), Dec:58
  a/c retrofit kit, Jun:64
  GLE, failing Hall effect sensor ('88-'90), Sep:25-26
780 (Volvo), a/c retrofit kit, Jun:64
840i (BMW), loose oil pump cover (March '94), Mar:74
850 (Volvo)
  hard starting ('92 on), Nov:96-97
  resetting the Service Reminder Lamp (SRL) ('92-'97), Jun:43
850i (BMW)
  5.0-liter, notchy shifting ('92), Nov:92-93
  stability control simulates misfire, Jul:63
900 (Saab)
  air bag light on ('95), Dec:58
  false MIL illumination ('90), Jan:46-47
  inoperative air conditioning compressor, Aug:19
  intermittent check engine light flashing ('89), Sep:83
  noisy stabilizer bar bushings ('92), Nov:94
  solving electrical glitches, Aug:16, 18
  SRS light on ('94), Oct:20
  too much clutch freeplay ('94), Jun:63
900S (Saab), no start ('89-'92), Aug:64
911 (Porsche)
  Carrera 2, tranny noises when cold ('90-'95), Dec:57
  Carrera
    engine oil leaks ('89), Sep:83
    loss of power ('89-'90), Aug:64
    no cruise control, Nov:94
  turbo, front brake disc precautions ('96), Jun:1
928 (Porsche)
  GT/S4, clutch chatter ('87-'93), Jun:63
  S4, adaptive memory and relearn ('87), Jan:48
929 (Mazda)
  3.6-liter, stalls after start when cold ('88-'89), Jan:48
  rough idle/cold stall ('89), Sep:83
940 (Volvo)
  a/c retrofit kit, Jun:64
  brake squeal ('92-'95), Dec:57
944 (Porsche)
  S2/turbo, foghorn noise while braking, Jan:1, Apr:55
  S, adaptive memory and relearn ('87), Jan:48
960 (Volvo)
  brake squeal ('92-'95), Dec:57
  oily a/c compressor ('93-'94), Apr:57
968 (Porsche), foghorn noise while braking, Jan:1
5000 (Audi)
  resetting the Oxygen Sensor warning lamp (OXS) ('84-'89), Jun:44
  steering groan ('89), Nov:92
6000 (Pontiac)
  LE, no heat complaint ('91), Jan:12-13
  release bearing/retainer destruction ('87-'89), Jun:32-34
9000 (Saab)
  air bag light on ('95), Dec:58
  false climate control DTCs ('90-'93), Apr:58
  false MIL illumination ('90), Jan:46-47
  tire rubbing ('92), Mar:70
9000S (Saab), no start ('89-'92), Aug:64
A4 (Audi)
  2.8-liter, rear main seal leak ('96), Dec:57
  sedan, false DTC P0461/16845 ('96), Apr:55
AAA Foundation for Traffic Safety, *The Older and Wiser Driver* video, Mar:75
Acceleration Simulation Mode (ASM)
  comparison of cost with BAR 90ET, Mar:32
  emissions testing for the future, Mar:26-29, 32
  vs. BAR 90 testing, Mar:27-28
Acclaim (Plymouth)
  3.0-liter
    cold hesitation, DTC13 ('89), Mar:68
    rough idle, stall, hesitation ('90),

1997 Motor Magazine Index

Mar:67
rough idle/oily sludge type deposits on throttle body/blade ('93), Mar:6, 8
Accomatic Transmission Parts, new catalog available, Dec:61
Accord (Honda)
1.8-liter, smoke on startup ('95), Sep:11-12, 16
2.0-liter, hard and/or no-start ('86), Aug:20-21
1998 tech report, Dec:20-21
LX, Automated Highway System (AHS) prototype ('96), Aug:48, 50
LXi, front brake caliper rattle noise ('89), Jun:1
misfiring under load ('90 on), Jan:18, 20
no 1-2 upshift ('84-'92), Nov:97
Accu-Turn
microprocessor wheel balancer, Nov:103
Model 7700 combination brake lathe, Feb:61
On-Car Lathe, Jun:68, Dec:64
wheel alignment equipment specs brochure, Oct:B19
ACDelco
air conditioning deodorizer, Nov:100
DuraStop brake line, Aug:73
new line of remanufactured rack and pinion steering gear, Apr:59
wire and cable catalog, Apr:65, Oct:B19
ACDelco Aftermarket, General Motors Service Parts Operations (SPO), counterfeit parts, Jan:44
Achieva (Oldsmobile)
2.3-liter, TCC chuggle ('93), Dec:50
longer-life brake pads ('92-'95), Jun:61, Aug:63
rear brake drag ('95), Aug:59
rough running/hesitation/tightly routed engine harness ('94), Feb:48
Acura, *See also specific models*
3.5RL, Global Positioning System (GPS), Aug:14-15
sudden no-start/uneven cranking rhythm/vacuum, Feb:20-21
ADS. *See* Association of Diesel Specialists (ADS)
Advanced Automotive Technologies, Autolife engine cleaning system, Feb:61
Advantage Lift Systems
acquisition of Globe Lift Co., Jul:66
environmental low volume retrofits for in-ground lifts, Sep:86
AE Clevite Engine Parts, "Think" Campaign, Aug:67
AERA. *See* Automotive Engine Rebuilders Association (AERA)
Aerostar (Ford)
3.0-liter, broken main cap bolts ('87-'88), May:115-116
4.0-liter, rear main seal tool ('90-'94), Jan:48
ignition module connector change ('94 on), Nov:93
speedometer wavers ('95), Oct:20
update ('97), Feb:45
AIADA. *See* American International Auto Dealers Association (AIADA)
Air bags
AIADA, liability of deactivating air bags, Mar:4
Automotive Service Association (ASA) reaction to NHTSA proposal, Jan:40, 43
deactivation approved by Insurance Institute for Highway Safety, Jul:58-59
National Highway Traffic and Safety Administration (NHTSA)
deactivation of, Mar:4
update, Mar:58
smart air bags on the SSC concept vehicle, Jan:14-15
Air conditioning systems
a/c clutch and cooling fan tips, Aug:32-36
Ford, O-ring caution, Feb:51
future of service, Mar:4
International Mobile Air Conditioning Association (IMACA), retrofit guides, Oct:36
modern cooling systems, Aug:23-26, 31
retrofit service tips, Apr:30-31, 34, 36-38
Airtek Inc., CATCO catalytic converter catalog, Oct:B19
AIS. *See* Automotive Information Systems (AIS)
AISI. *See* American Iron and Steel Institute
Alden Corp., Drill-Out power extractors, Oct:B19
All Pro/Bumper to Bumper, management video series, Oct:B19
Allanté (Cadillac), noisy accessory drive belt ('93), Oct:24, 28
ALLDATA
agreement with MOTOR Publications, Jan:40
Series 295 technical service bulletin database, Jan:53, Feb:62, Mar:85, Sep:95, Oct:B19
web site address, Apr:59
AlliedSignal, FRAM Food Drive, May:105
AllTest, Model 9100 Allsweep Tester, Universal Testing telemarketing scam, May:88-90, 95-96
Altima (Nissan)
1998 tech report, Dec:26
expanded line of remanufactured transmissions, Jun:64
American International Auto Dealers Association (AIADA), liability of deactivating air bags, Mar:4
American Iron and Steel Institute (AISI)
developing new fuel economy technology, Jun:48, 51
light truck structure study released, Jun:51
American Petroleum Institute (API)
new oil classification, Apr:48-49
Used Oil and Oil Filter Recycling workshops, Jan:44
American Society of Testing and Materials (ASTM), reaction to new oil classification, Apr:48-49
Amigo (Isuzu)
2.3-liter, high idle ('89-'90), Feb:51-52
2.6-liter, hard starting, fuel pump problems ('89-'90), Mar:70
high idle ('89-'91), Jan:47
AMRA. *See* Automotive Maintenance and Repair Association
Anticounterfeiting Consumer Protection Act, ACDelco Aftermarket, Jan:44
APAA. *See* Automotive Parts and Accessories Association (APAA)
API. *See* American Petroleum Institute (API)
APRA. *See* Automotive Parts Rebuilders Association (APRA)
ASA. *See* Automotive Service Association (ASA)
ASAMI. *See* Automotive Service Association Management Institute (ASAMI)
ASE. *See* National Institute for Automotive Service Excellence (ASE)
ASIA. *See* Automotive Service Industry Association (ASIA)
ASM. *See* Acceleration Simulation Mode (ASM)
Aspire (Ford), brake roughness ('94-'95), Aug:65-66
Associated Equipment, Model 8500A alternator/starter tester, Jun:65
Association of Diesel Specialists (ADS), TechCert Technician Recognition Awards, Jan:49
ASTM. *See* American Society of Testing and Materials (ASTM)
Astro (Chevrolet)
4.3-liter, bad fuel pump relay ('93-'94), Jan:48
tough front end alignment, Jan:46
ATP
flywheel shims, Jan:50
lockup converter delay harnesses, Sep:88
transmission fluid additive, Aug:70
Audi, *See also specific models*
w/center takeoff steering racks, improper tie-rod installation, Oct:24
Aurora Industries, Squeak Relief brake finishing treatment, Aug:68
Aurora (Oldsmobile)
4.0-liter
fuel pressure regulator service ('95), May:112
noisy accessory drive belt ('93-'95), Oct:24, 28
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Auto Shop-Aid, transmission fluid recovery system, Mar:78, Sep:90
Auto Test System, Scanmaster Pro scanner, May:125
Auto Value Associates Inc.
1000 prepaid ASE test registrations, Apr:49-50
scholarships available, Jul:66
Autodiagnos, ACE information management software, Aug:73, Sep:36, 91, Oct:B20
Automotive Aftermarket Industry Week, Mar:75
AAIW Interactive Show Directory database, Aug:67
Automotive Electronic Services, AES Wave! information management software, Apr:61, Sep:40
Automotive Electronics Conference, tomorrow's electromechanical vehicles, Jan:14-15
Automotive Engine Rebuilders Association (AERA)
Geo Metro cylinder head oil restrictor, May:116
proper piston/rod assembly, Jan:46
web site address, Nov:39, Dec:61
Automotive Information Systems Inc. (AIS), used car reliability info on CarPoint website, Sep:71-72
Automotive Lift Inst., lift point guide, Dec:64
Automotive Maintenance and Repair Association (AMRA), Motorist Assurance Program (MAP), May:98
Automotive Parts and Accessories Association (APAA), creation of scholarship program, May:117
Automotive Parts Rebuilders Association (APRA)
1997 Membership Directory, Jul:66
researching field problems with Ford IAR alternators ('84-'94), Jul:28-29
web site address, Nov:39
Automotive Service Association (ASA)
A Guide to the 105th U.S. Congress, Sep:86
car dealer limits, Feb:56
reaction to air bag proposal, Jan:40, 43
School-to-Work Educational Resource Guide, May:117
technician credentials survey results, Jul:2
web site address, Sep:86, Nov:39
Automotive Service Association Management Institute (ASAMI)
approves S.M.A.R.T. Program, Jun:64
Emil Stanley Merit Award recipients, Feb:59
Hiring the Superstars! self study course, Dec:61
Managing Your Business for Profit self study course, Dec:61
Automotive Service Industry Association (ASIA), web site address, Nov:39
Automotive Test Systems, Model 8700 DIS and KV tester, Dec:63
Automotive Warehouse Distributors Association (AWDA), creation of scholarship program, May:117
AutoTool, total transmission service fluid flusher, Sep:40
Avenger (Dodge)
2.0-liter, engine miss ('95), May:113
2.5-liter, intermittent no-start and MIL on ('95), Jul:60
AWD wagon (Volvo), 1998 tech report, Dec:35
AWDA. *See* Automotive Warehouse Distributors Association (AWDA)

B

B4000 (Mazda), exhaust ticking ('95), May:116
BAR. *See* Bureau of Automotive Repair (BAR)
Bars Leaks, three new stop-leak and conditioner products, Aug:67
BBK Performance, Mustang (Ford), adjustable strut mounts ('79-'93), Apr:62
Beck/Arnley Worldparts Corp.
1996 New Clutch Sets catalog, May:117, Dec:61
1996 Rotating Electrical Products, Apr:59
import engine parts, May:125
import starters and alternators poster, Mar:75
injector cleaning kit, Dec:62
new fail-safe import thermostats, Apr:65
OE-quality clutch sets for imports, Mar:80
Pro Pack brake pad kits for imports, Jul:70
switches for imports, Jun:68
timing components kit, Aug:74
Benwil Lifts
GPI-9 environmentally friendly lift, Dec:62
super duty lift system, Nov:103
Beretta (Chevrolet)
2.2-liter, hesitation/cold stall/rough running ('92-'93), May:115
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
ABS indicator lamp on/DTCs 23/24 or 34/35 ('95-'96), Mar:1
high brake pedal effort ('92-'93), Jan:1
longer-life brake pads ('92-'95), Jun:61, Aug:63
release bearing/retainer destruction ('87-'89), Jun:32-34
Berryman Products
brake cleaners, May:120
total fuel systems cleanup, Feb:62, Aug:73
Beta Tools, PitLane Products, US importer of, May:120, Aug:73, Oct:36
Big Lug Tools, Load-A-Lug impact sockets, Jun:65
Black Gold Corp., waste oil fired boiler, Jan:49, Aug:67
Blazer (Chevrolet)
2.8-liter, reman engine running poorly/oil in air cleaner ('84), Jul:48, 50
4.3-liter, bad fuel pump relay ('94), Jan:48
BMW, *See also specific models*
3/5-Series, corroded harness connector ('88 on), Oct:17
electrical problems, Oct:14, 17
BMW of North America, Service technicians Education Program (S.T.E.P.), Aug:67
Bonneville (Pontiac)
3.8-liter, erratic misfire at 45 to 60 mph ('93), Feb:6, 8, 65
3800 V6
revised engine torque specs ('92-'94), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52
service manual update, YES/NO boxes reversed ('93-'95), Jul:65
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
poor performance ('89), Feb:19
starter motor change ('95), Sep:84
Bosch, replacement Ford IAR alternators, Oct:B20
Brake System Service Slants, *See also* Brakes; **Service Slants**
300ZX (Nissan), front brake clunk in reverse ('90), Jun:1
750i (BMW), noisy rear brakes ('90), May:1
911 (Porsche), turbo, front brake disc precautions ('96), Jun:1
944 (Porsche), S2/turbo, foghorn noise while braking, Jan:1
968 (Porsche), foghorn noise while braking, Jan:1
Accord (Honda), LXi, brake caliper rattle noise ('89), Jun:1
Aurora (Oldsmobile), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Beretta (Chevrolet)
ABS indicator lamp on/DTCs 23/24 or 34/35 ('95-'96), Mar:1
high brake pedal effort ('92-'93), Jan:1

Bonneville (Pontiac), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Breeze (Plymouth), grinding or squeaking front brakes ('95-'96), Mar:1
Caravan (Dodge), ABS system activates below 10 mph ('96), May:1
Cavalier (Chevrolet), high brake pedal effort ('92-'93), Jan:1
Cherokee (Jeep), banging noise from rear axle area ('97), Sep:1
Cirrus (Chrysler), grinding or squeaking front brakes ('95-'96), Mar:1
Concorde (Chrysler), ABS lamp on intermittently ('93), Jan:1
Concours (Cadillac), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Corsica (Chevrolet)
ABS indicator lamp on/DTCs 23/24 or 34/35 ('95-'96), Mar:1
high brake pedal effort ('92-'93), Jan:1
Cutlass (Oldsmobile), Supreme, brake noise, high pedal effort, decreased pad life ('88-'93), May:1
DeVille (Cadillac), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Eclipse (Mitsubishi), rear brake squeak ('90-'91), Sep:1
Econoline (Ford), 4-wheel ABS lamp on/false codes in memory ('94-'96), Jun:1
Eighty Eight (Oldsmobile), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Eldorado (Oldsmobile), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Escort (Ford), front caliper knock during moderate braking ('91-'96), May:1
Golf (Volkswagen)
rattling noise at front brakes ('90-'91), Mar:1
w/cruise control, brake dragging and noise ('94), Mar:1
Grand Cherokee (Jeep), rattle in rear wheel ('94), Jan:1
Grand Prix (Pontiac), brake noise, high pedal effort, decreased pad life ('88-'93), May:1
Hombre (Isuzu), false ABS DTCs 35, 36 and 37 ('96), Mar:1
Honda, ABS rear wheel speed sensor harnesses reversed ('97), Sep:1
Intrepid (Dodge), ABS lamp on intermittently ('93), Jan:1
Jetta (Volkswagen)
rattling noise at front brakes ('90-'91), Mar:1
w/cruise control, brake dragging and noise ('94), Mar:1
LeSabre (Buick), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
LSS (GM), buzz/rattle from instrument panel when brake pedal is depressed ('96-'97), Sep:1
Lumina (Chevrolet), brake noise, high pedal effort, decreased pad life ('90-'93), May:1
MPV (Mazda), ABS indicator stays on and DTC53 stored in memory, Sep:1
Neon (Plymouth/Dodge), rear brake chirp ('95-'96), Jun:1
Ninety Eight (Oldsmobile), buzz/rattle from instrument panel when brake pedal is depressed ('95-'96), Sep:1
Park Avenue (Buick), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Regal (Buick), brake noise, high pedal effort, decreased pad life ('88-'93), May:1
Regency (Buick), buzz/rattle from instrument panel when brake pedal is depressed ('96-'97), Sep:1
Riviera (Buick), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Sable (Mercury)
ABS lamp on, DTC stored in memory ('96), Sep:1
brake vibration during stop ('86-'93), Jan:1
Sebring (Chrysler), convertible, rear brake chirp ('96), Jun:1
Sentra (Nissan), ABS Self-Check clunk noise ('91), Jun:1
Seville (Cadillac), buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Stratus (Dodge), grinding or squeaking front brakes ('95-'96), Mar:1
Taurus (Ford)
ABS lamp on, DTC stored in memory ('96), Sep:1
brake vibration during stop, ('86-'93), Jan:1
police and SHO, brake vibration ('89-'93), Jan:1
Town and Country (Chrysler), ABS system activates below 10 mph ('96), May:1
Tracer (Mercury), front caliper knock during moderate braking ('91-'96), May:1
Vision (Eagle), ABS lamp on intermittently ('93), Jan:1
Voyager (Plymouth), ABS system activates below 10 mph ('96), May:1
Windstar (Ford), brake MIL illuminates immediately after stopping ('95-'96), Mar:1
XJ-S (Jaguar), premature rear brake pad wear, Mar:1
Brakes, *See also* **Brake System Service Slants**
exports denied to Japan, May:109
on-car lathe, Jun:28, 30
Raybestos, D_3EA certified brake pads, Jan:49, 53
runout and thickness variation, Jun:26-28
Bravada (Oldsmobile)
4.3-liter, bad fuel pump relay ('94), Jan:48
exhaust noise ('92-'93), Oct:28
Brayton Engineering, new Aurora V8 engine, May:32
Breeze (Plymouth), grinding or squeaking front brakes ('95-'96), Mar:1
Bright Solutions, blue light leak detectors, Apr:41-42
Bronco (Ford)
4.9-liter, hesitation/surge ('91-'92), Nov:92
5.0/5.8-liter
belt chirping ('87-'88), Jun:62
strange electrical symptoms ('92-'95), Mar:73
electrical problems ('94), Nov:97
harsh shifting and codes ('89-'94), Oct:24
Bryco by Carfel
timing belts and tensioners, Oct:B20
Toyota A340F filter and filter kit available, Dec:61
Buick
3.8-liter, intermittent misfire ('93), Jul:6, 10, 12
3800 V6, testing for ignition coil breakdown, Oct:6
PermaDry Plus Gasket for oil pan ('85'95), Oct:B21
Bureau of Automotive Repair (BAR)
BAR 90 vs. ASM testing, Mar:27-28
comparison of BAR 90 costs with ASM, Mar:32
Electronic Transmission (ET), cracking down on Smog Check shop fraud, Jun:4
results of studies, Mar:28
testing lanes, Mar:26
Business Sense
the basics of selling service and repairs, Jan:33-36, Mar:51-54
charging for diagnostic time, Jul:51-52, 53-54
delegating authority, Nov:79-82
handling comebacks, Sep:65-68
safety inspections, a service and sales tool, May:97-100
six selling techniques, Mar:52-54
BWD Automotive
new crank angle sensor, May:119
Sure Spark wire sets, Oct:B20
web site address, Aug:67

C

C220/C280 (Mercedes-Benz), leaky trunk, Dec:58
C3500HD truck (GMC)
7.4-liter
no speedometer/RWAL brake malfunction, Jun:9, 12
stuck in second gear, Jun:9, 12
premature tire and brake wear ('91-'94), Aug:62
C/K-Series truck (GM)
4.3-liter, sustained detonation ('92), Mar:65
5.7-liter, cold sag/hesitation/sulfur smell ('93), May:114
6.5-liter
black smoke after engine work ('94-'95), Mar:68
stall, poor throttle response ('94), Sep:82
7.4-liter, low power/overheating ('90-'93), Oct:28-29
clutch master cylinder breakage ('88 on), Jul:63
temperature control lever moves by itself ('88-'94), Jul:60
update ('97), Feb:45
Cadillac, *See also specific models*
4100-engine, multiple potentially fatal problems, Jul:46-47
Radio Data System (RDS), Nov:89
California Air Resources Board (CARB)
help for aftermarket manufacturers of OBDII equipment, May:102
new emissions standards for heavy-duty diesel engines, Feb:58
web site address, Nov:40
California Auto Tech, Snake-Bit EGR passage cleaner, May:27, Jul:69, Sep:44
CAM. *See* Championship Association of Mechanics (CAM)
Camaro (Chevrolet)
3.4-liter
driveability reprogramming ('93), Aug:66
new "Flash" EEPROM to correct numerous driveability symptoms, May:113
5.0/5.8-liter, MIL on with DTC22 stored ('91), Apr:58
5.7-liter
chuggle and/or surge at low rpm while accelerating, Mar:67
noisy accessory drive ('93), Oct:31
Camry (Toyota)
1998 tech report, Dec:22-23
California 4-cylinder, new oxygen sensor ('97), Mar:18, 21
inoperative air conditioning ('88), Sep:16, 18-19
may not start in wet weather ('87-'91), Jul:22, 25
Capri (Mercury), brake roughness ('82-'86) ('91-'94), Aug:65-66
Caprice (Chevrolet)
5.0/5.7-liter, MIL on with DTC22 stored ('91), Apr:58
no cruise control operation (sedans) or no/intermittent cruise control operation (wagons) ('92-'93), Mar:39-40
Caravan (Dodge)
3.0-liter
cold hesitation, DTC13 ('89), Mar:68
rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-'93), Aug:59
ABS engages below 10 mph ('96), May:1, Aug:61
cracked fuse block ('94), Aug:63
poor heater and/or air conditioner performance ('84-'94), Feb:51
power steering pump snow shield ('91-'95), Jan:47
seat fuse box cover correctly ('96), Jun:56-57
update ('97), Feb:40
CARB. *See* California Air Resources Board (CARB)
Cardealerjobs.com, web site address, Dec:61
Cardone Industries, Ride Saver Plus reman struts, Nov:99
CarPoint, web site address, Sep:71
CARQUEST, Excellence Award recipient, May:117
CARS, *Shop Management Tools For Success,* Jan:53, May:125, Jun:71, Jul:75, Aug:74, Sep:95, Oct:B23, Nov:103, Dec:64
CASE. *See* Continuing Automotive Service Education (CASE)
Cavalier (Chevrolet)
2.0-liter, ASM dyno test ('87), Apr:19, 21
2.2-liter, hesitation/cold stall/rough running ('92-'93), May:115
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
high brake pedal effort ('92-'93), Jan:1
longer-life brake pads ('92-'95), Jun:61, Aug:63
release bearing/retainer destruction ('87-'89), Jun:32-34
CCAR. *See* Coordinating Committee for Automotive Repair (CCAR)
CCAR-*Green*Link
receive Hammer Award, May:117
web site address, Nov:40, Dec:61
Celebrity (Chevrolet), release bearing/retainer destruction ('87-'89), Jun:32-34
Central Telephone Company (Sprint), unacceptable refrigerant use, Aug:50, 52
Central Tools
Brake Force Rotor Gage, Jun:65
valve seat measuring tools, May:118
Centrum, PHD hardware device for Internet access, Sep:86
Century (Buick)
new design tie rod ends ('93-'95), May:119
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Century Manufacturing, acquires P&F Technologies, Aug:67
Champion Pneumatic, Advantage series compressors, Sep:92, Oct:B20
Championship Association of Mechanics (CAM), IndyCar crew members organization, May:102
Chassis Cab (Dodge)
3500 Series dualie, brake drift ('94-'95), Jul:60, 63
diesel, power loss, harsh shifts ('94), May:112-113
Cherokee (Jeep)
2.5/4.0/5.2-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
banging noise from rear axle area ('97), Sep:1
clutch slippage ('94), Jun:34, 35
update ('97), Feb:40
water damaged radio ('93), Aug:61
Chicago Pneumatic, higher performance improved regulator, Apr:57, 65
Childs and Albert, engine performance parts catalog, Dec:61
Chrysler Corp., *See also specific models*
2.2/2.5-liter
cracked head, Jul:48
DTC13/14 on, Mar:36-37
plugged radiator/overheating and blown head gasket, Jul:46
proper piston/rod assembly ('81-'95), Jan:46
3.0-liter, DTC13/14 on, Mar:36-37
evaporator part numbers by model, Apr:56
foul a/c odor ('92), Apr:55-56
Tech Authority catalog, Oct:B20
w/center takeoff steering racks, improper tie-rod installation, Oct:24
Cirrus (Chrysler)
gauges freeze up ('95), Nov:92
grinding or squeaking front brakes ('95-'96), Mar:1
insufficient a/c output ('95), Jun:58
intermittent electrical glitches ('95), Oct:31
rear suspension changes ('95), Oct:28
slow or no cranking ('95), Dec:57
slow-speed steering shudder ('95),

1997 Motor Magazine Index

May:115
updated body control modules ('95), Jul:65
Civic (Honda)
1.5-liter, rough idle/shifter locked ('89-'91), Nov:93
brake vibration ('92-'94), May:112
harsh shifting ('94), Mar:73-74
horn randomly blows in cold weather ('90), Feb:51
intermittent starter grind ('89-'90), Jul:63
no 1-2 upshift ('84-'93), Nov:97
Classic Tool Design
Hoon-Yocker, closed-loop refrigerant flushing machine, Apr:42, 46
Sly Fox No. 22-2150, air-operated refrigerant recovery system, Apr:42
Clayton Industries, ASM dynamometer meets BAR requirements, Jul:66
Clean Burn Inc.
used oil furnaces, Oct:B20, Nov:103
web site address, Jun:64
CLK (Mercedes-Benz)
1998 tech report, Dec:26, 35
Ultra Low Emissions Vehicle (ULEV), introduced ('98), May:110
Club Wagon (Ford), update ('97), Feb:45
Comptech Machine, new Aurora V8 engine, May:32
Computers, *See also* Internet; World Wide Web (WWW)
AAIW Interactive Show Directory database, Aug:67
ALLDATA, Series 295 technical service bulletin database, Jan:53, Feb:62, Sep:95, Oct:B19
Autodiagnos, ACE information management system, Sep:36, 91, Oct:B20
Automotive Electronics Services, AES Wave! information management software, Apr:31, Sep:40
CD-ROM based technical materials, Apr:2
computerized shop management and repair systems, Jan:22-24, 26
diagnosing strategies for computer controlled vehicles, Feb:22-24, 26, 28
Edge Diagnostic Systems, Dyno-Tech Diagnostic software, Sep:47-48
John Bean Company, CAS shop management system, Oct:B22
Mitchell Repair, CD-ROM transmission repair information, Nov:104
MOTOR Magazine, **Service Slants** on disk, Jun:71, Sep:95, Nov:107, Dec:64
Mr. Gasket Performance Group, DeskTop Dyno/DragStrip engine building simulation software, Jul:66
NEBS Inc., Form Magic software, May:117
protecting your data from crashes, viruses and spies, Jan:26
Quick Quote, estimating software package, May:117
Concorde (Chrysler)
3.5-liter, buck and/or miss at cruising speed ('93), Feb:52
ABS light on intermittently ('93), Jan:1
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
new V6 engine ('98), Sep:55-56
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Concours (Cadillac)
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
noisy accessory drive belt ('94), Oct:24, 28
Contact East, test equipment, tools & supplies catalogs, Jun:64, Jul:66, Oct:36
Continental (Lincoln)
3.0/3.8-liter, no crank ('92-'95), May:112
brake roughness ('82-'95), Aug:65-66
lack of power/hesitation/stalling with hard restart ('93-'94), Dec:50
nonfunctional blower cover motor ('93-'94), Aug:61-62
returnless fuel injection ('98), Sep:51-52
Continuing Automotive Service Education (CASE), evaluation/certification of training providers, Feb:4
Contour (Ford)
2.0-liter, EGR valve eliminated ('98), Sep:52, 54
brake roughness ('95), Aug:65-66
Cooper Automotive
donation to high school automotive training program, May:117
Power Path spark plug wire set, Mar:76
product donation, Oct:36
Cooper Industries, web site address, Mar:75
Coordinating Committee for Automotive Repair (CCAR)
automotive education program study results, Jun:52
Interactive Satellite Career Fair, Jul:56, 58
Corolla (Toyota)
1998 tech report, Dec:22-23
transmission noise ('89), Dec:58
Corrado (Volkswagen)
hard/no-start, Aug:64
rear tire wear, Jun:61-62
Corsica (Chevrolet)
2.2-liter, hesitation/cold stall/rough running ('92-'93), May:115
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
ABS indicator lamp on/DTCs 23/24 or 34/35 ('95-'96), Mar:1
high brake pedal effort ('92-'93), Jan:1
longer-life brake pads ('92-'95), Jun:61, Aug:63
release bearing/retainer destruction ('87-'89), Jun:32-34
Corvette (Chevrolet)
fifth generation ('97), Feb:55
LT1 engine, Opti-Spark distributor problems, May:20-21
Cottman Transmission Systems
35th anniversary, Mar:75
web site address, May:117
Cougar (Mercury)
3.8-liter, exhaust moan ('92-'95), Jan:47
3.8/4.6-liter, sluggish shifting/stumble ('94), Jun:58, 61
brake roughness ('82-'95), Aug:65-66
ignition module connector change ('94 on), Nov:93
County (Land Rover), driveline vibration ('94-'95), Oct:33
CPS Products, corona discharge leak detectors, Apr:41-42
CR-V (Honda), SUV, update ('97), Feb:45-46
Craftsman, *Power and Hand Tools* catalog, Oct:36
CRC Industries, QD Electronic Cleaner, Mar:76
Crown Remanufacturing, *Constant Velocity Driveshafts* catalog, Dec:61
Crown Victoria (Ford)
4.6-liter, rough idle, miss, stumble ('91-'92), Jul:60
brake roughness ('92-'95), Aug:65-66
erratic shifting ('92-'95), Mar:70
ignition module connector change ('94 on), Nov:93
Team ASE Racing funny car, May:85
Crown Victoria NGV (Ford), first alternative fuel taxicab, Nov:90-91
CuproBraze, copper-brass radiators, Aug:67
Cutlass (Oldsmobile)
Calais, longer-life brake pads ('91), Jun:61, Aug:63
Cierra/Cruiser, new design tie rod ends ('93-'95), May:119
Supreme
2.8-liter, intermittent stalling/tuneup, Oct:22
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
brake noise, high pedal effort, decreased pad life ('88-'93), May:1
Cyclo Industries, diesel injector cleaner, Aug:70

D

D21 truck (Nissan)
2.4-liter, transfer case rattle, Jul:64
hard shifting ('90-'91), Jun:39
Dakota (Dodge), 4X2 Sport, update ('97), Feb:40
Dana Corp.
NASCAR line of oil and air filters, Jan:49
new oil filter design, Nov:90
Dana (Jeep), update ('97), Feb:40
Darex, Drill Doctor drill sharpener, Aug:73, Oct:B20
Daytona (Dodge), 3.0-liter, rough idle, stall, hesitation ('90), Mar:67
Delphi Saginaw Steering Systems, E-Steer electric power steering system, May:102, 105
DeltaTRAK, Optex Thermo-Hunter IR-3LF Infrared Thermometer, Sep:38, Dec:63
DeVille (Cadillac)
4.0-liter, fuel pressure regulator service ('95), May:112
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
false a/c codes ('88-'89), Apr:57
hesitation on acceleration ('87), Mar:74
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Diagnosing
a/c clutch and cooling fan tips, Aug:32-36
charging for time, Jul:51-52, 53-54
exhaust gases vs. tailpipe gases, Feb:23-24
modern cooling systems, Aug:23-26, 31
with On-board Diagnostics System (OBD) codes, Feb:30-32, 34, 39
oxygen sensor as a tool, Nov:35-37
second generation On-board Diagnostics Systems, Feb:30-32, 34, 36-38
strategies for computer controlled vehicles, Feb:22-24, 26, 28
technician worksheets, Feb:23-24
terminal engine problem diagnostic tree, Jul:48
terminal engine problems, Jul:45-48, 50
tips on mastering wiring diagrams, Jul:30-31, 33-34, 36
Dictaphone Corp., Synergy, Feb:58
Discovery (Land Rover), driveline vibration ('94-'95), Oct:35
DL (Subaru), inoperative heater ('89), Dec:58
Douglas Battery, ISO 9000 certification, Feb:59
DuPont
agreement with Freudenberg-NOK for Vespel parts, Nov:100
refrigerant recovery and recycling agreements, Mar:75, Aug:67
DuPont Suva Refrigerants, training seminars, Jul:66
Durango (Dodge), update ('97), Feb:40
Dynasty (Dodge)
3-liter
cold hesitation, DTC13 ('89), Mar:68
rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-1/2-'93), Aug:59
DynoMax Performance Exhausts, new line of high-performance mufflers, Feb:59

E

E320 (Mercedes-Benz)
no oxygen sensor data ('95), Oct:20
special impulse counter scan tool ('94), Oct:20
E-150 truck (Ford), replacing the ABS HCU ('94), Oct:20
E-250 truck (Ford), 7.3-liter, lack of power ('95), Aug:59, 61
E-350 truck (Ford)
7.3-liter, lack of power ('95), Aug:59, 61
fading brake pedal ('93), Jun:14, 16-17
Earl's Performance Products, Hyperfirm brake lines, Sep:90
EASE Simulation Inc., Top 20 Tools award, Mar:92
East Penn Manufacturing, Lynx Toolless Terminals, Jun:66-67
Eaton Corp., web site address, Jun:64
Eclipse (Mitsubishi)
2.0-liter, misfiring and codes ('95), Jul:64
rear brake squeak ('90-'91), Sep:1
Econoline (Ford)
4-wheel ABS lamp on/false codes in memory ('94-'96), Jun:1
4.9-liter, hesitation/surge ('91-'92), Nov:92
5.0/5.8-liter, belt chirping ('87-'88), Jun:62
7.3-liter diesel, no start ('95), Sep:80, 82
harsh shifting and codes ('89-'94), Oct:24
update ('97), Feb:45
Edge Diagnostic Systems, Dyno-Tech Diagnostic software, Sep:47-48
Editor's Report
Automotive Service Association (ASA)
School-to-Work Educational Resource Guide, Dec:4
technician credentials survey results, Jul:2
automotive service industry scams, May:5
Bureau of Automotive Repair (BAR), cracking down on Smog Check shops, Jun:4
the changing face of retail auto sales, Aug:5
the difficulty in selecting Top 20 Tools, Sep:4
evaluation/certification of training providers, Feb:4
finding needed service information, Apr:2
future of air conditioning system service, Mar:4
getting involved in education, Dec:4
liability of deactivating air bags, Mar:4
Motorist Assurance Program (MAP), Jul:2
National Census of Fatal Occupational Injuries, Nov:4
safety in the workplace, Nov:4
sixth annual *Source Guide* gets better, Oct:2
So You Want to Become an Auto Technician review, Jan:4
Society of Automotive Engineers (SAE), International Congress and Exposition, Apr:2
the value of "shop sense," Jan:4
Eighty Eight (Oldsmobile)
3800 V6
revised engine torque specs ('92-'94), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52
service manual update, YES/NO boxes reversed ('93-'95), Jul:65
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
starter motor change ('95), Sep:84
Elantra (Hyundai)
California 1.8-liter, cold-start stalling (prior to 10/13/92), Mar:73
federal 1.8-liter, cold-start stalling (prior to 12/1/92), Mar:73
Eldorado (Cadillac)
4.0-liter, fuel pressure regulator service ('95), May:112
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
noisy accessory drive belt ('93-'94), Oct:24, 28
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Electronic Transmission (ET), cracking down on smog check shop fraud, Jun:4
Emi-Tech
fuel system analyzer, Sep:38, Oct:B21
Vacutec vacuum leak detector,

Sep:38, Oct:B21
Emissions, *See also* **Smog Check**
Acceleration Simulation Mode (ASM), Mar:26-29, 32
ASM vs. BAR 90 testing, Mar:27-28, 32
California Air Resources Board (CARB), new standards for heavy-duty diesel engines, Feb:58
Engine Connection, remanufactured transmissions, May:119
Enginetech, valve stem seal identification chart, Nov:100
Enhanced Evaporative Emission Control, tech preview of the 1998 models, Sep:50-51
Environmental Protection Agency (EPA)
admits error in tougher air quality standards, Jun:53
HC-12a banned, Aug:50, 52
legalities of refrigerants, Apr:22-24, 27-28
sham refrigerant retrofits, Jun:48
web site address, Nov:40
Environmental regulations, coping with, Mar:45-46, 48
Environmental Systems Products Inc. (ESP)
ASM5015/2525 in-ground dyno beta site, Apr:18-19, 21
testing lanes, Mar:26
Envirotech Systems, private label automotive refrigerants, Apr:59
EPA. *See* Environmental Protection Agency (EPA)
Eppco Enterprises, custom fender covers, Mar:78
Equipment and Tool Institute (ETI)
50th anniversary, May:108-09
1997 Member Training Directory, Nov:100
annual meeting, Jan:38-39
ES300 (Lexus), inaccurate fuel gauge reading (prior to 9/27/91), Mar:67
Escort (Ford)
1.6-liter, cracked head, Jul:48
1.8/2.2-liter, hard start/hesitation/rough idle ('91-'92), Oct:29
1.9-liter
buck and/or jerk at highway speed ('86-'90), May:116
whining timing belt ('94), Jan:46
brake roughness ('92-'95), Aug:65-66
EGR valve eliminated ('98), Sep:52, 54
front caliper knock during moderate braking ('91-'96), May:1
ignition module connector change ('94 on), Nov:93
MTX worn release bearing quill ('88-'90), Jun:34
ESP, SystemOne emissions inspection system, Oct:B21
Esteem (Suzuki), 1998 tech report, Dec:35
ET. *See* Electronic Transmission (ET)
ETI. *See* Equipment and Tool Institute (ETI)
EUVL. *See* Expected Useful Vehicle Life (EUVL)
EV1 technician training, Mar:56-58
EV Plus (Honda), debut, Mar:59-60
Everco Temperature Control Products
1997 Master Temperature Control catalog, Jun:64
A/C Retrofit Manual, Apr:59
back-to-basics approach to power steering diagnosis and service, Sep:78
Power Steering Pumps and Gears Catalog, Jan:49
refrigerant flushing gun, Apr:44
Excel (Hyundai)
EGR solenoid valve noise ('90), Aug:61
intermittent no-cranks ('89-'92), Sep:80
Expected Useful Vehicle Life (EUVL), study results, Jun:52
Expedition (Ford), update ('97), Feb:40, 45
Explorer (Ford)
4-liter, rear main seal tool ('91-'94), Jan:48
caster/camber adjusting kit available ('95 on), Mar:78-79
cold-startup noise ('92-'93), Dec:57
ignition module connector change ('94 on), Nov:93
update ('97), Feb:45
Eye on Electronics
automotive lighting systems of the past and future, Nov:28-31
Camry (Toyota), California 4-cylinder, new oxygen sensor ('97), Mar:18, 21
Corvette (Chevrolet), LTI engine, Opti-Spark distributor problems, May:20-21
electronics of the future, Jan:14-15
Ford, field problems with IAR alternators ('84-'94), Jul:26, 28-29
minimizing returns on alternator replacements, Sep:28, 31-32

F

F300 (Mercedes-Benz), three wheel concept vehicle, Dec:48-49
F-150 truck (Ford), *See also* F-Series truck (Ford)
Team ASE Racing NASCAR, Craftsman Truck Series, May:84, 86
F-250 truck (Ford), *See also* F-Series truck (Ford)
7.3-liter
diesel, no start ('95), Sep:80, 82
lack of power ('94-'95), 61, Aug:59
Super Duty, refrigerant loss ('95), Apr:58
clutch won't disengage ('93-'95), Oct:35
F-350 truck (Ford), *See also* F-Series truck (Ford)
7.3-liter
diesel, no start ('95), Sep:80, 82
lack of power ('94-'95), Aug:59, 61
Super Duty, refrigerant loss ('95), Apr:58
clutch won't disengage ('93-'95), Oct:35
F-Series truck (Ford), *See also specific models*
4.9-liter, hesitation/surge ('91-'92), Nov:92
5.0/5.8-liter
belt chirping ('87-'88), Jun:62
strange electrical symptoms ('92-'95), Mar:73
7.3-liter Super Duty, clutch won't disengage ('93-'95), Oct:35
7.3-liter Super Duty, lack of power ('94-'95), Aug:59, 61
binding clutch ('83-'89), Sep:78
electrical problems ('94), Nov:97
harsh shifting and codes ('89-'94), Oct:24
Fasnacht Equipment, Tool Kaddy, Jun:66
Federal-Mogul
National Redi-Seal program, Aug:67
Sealed Power Engine and Transmission Mounts, Jan:49
FEDWORLD, web site address, Oct:22, Nov:40
Fel-Pro Inc.
1997 Master Gasket Catalog, Nov:100
1997 Medium and Heavy Duty Truck and Tractor catalog, Dec:61
Automotive Technicians Scholarship Program awards, Jan:49
crush-resistant head gasket for Honda, Apr:59
Engine$aver crankshaft repair sleeves, Dec:64
Engine$aver cylinder head bolt sets, Nov:103
engine sealing kit, Jan:50
improper gasket installations, Jan:48
improved head gasket for Toyota, Dec:62
new head gasket for Chevy small block engines, May:117
PermaDry Plus Gasket for Buick oil pan ('85'95), Oct:B21
problem-solving head gasket, Jul:69
sealing gasketless engine parts, Sep:78
SteelGard head gaskets, Sep:91
Tech Network brochure, Mar:75
Tru-Form oil pan gasket set, Feb:61
Ferodo America Inc., SpectraOne disc brake pads, May:120
Festiva (Ford)
brake roughness ('88-'93), Aug:65-66
gear clash/hard shifting ('88), Jun:57
Filter Manufacturers Council (FMC)
Used Filter Hotline number, Jan:44
Used Oil and Oil Filter Recycling workshops, Jan:44
Firebird (Pontiac)
3.4-liter
driveability reprogramming ('93), Aug:66
new "Flash" EEPROM to correct numerous driveability symptoms, May:113
5.7-liter
chuggle and/or surge at low rpm while accelerating, Mar:67
noisy accessory drive ('93), Oct:31
rear brake proportioning valve eliminated ('98), Sep:54
Firenza (Oldsmobile), release bearing/retainer destruction ('87-'89), Jun:32-34
Fleetwood (Cadillac)
false a/c codes ('88-'89), Apr:57
hesitation on acceleration ('87), Mar:74
Fluke Corp.
98 Series II Auto ScopeMeter, Apr:62, Nov:104
new multimeter warranty, Feb:59
Fluoro Tech
digital electronic refrigerant recharging scale, Jul:68
refrigerant recovery and recycling agreement with DuPont, Mar:75
FMC. *See* Filter Manufacturers Council (FMC)
Ford Motor Company, *See also specific models*
3.8-liter, CFI V6, DTC22 (MAP sensor) won't go away, Mar:36
7.3-liter, diesel Super Duty, no start ('95), Sep:80, 82
air conditioning O-ring caution, Feb:51
Bosch replacement IAR alternators, Oct:B20
EGR monitoring, Feb:37
field problems with IAR alternators ('84-'94), Jul:26, 28-29
On-board Diagnostics System (OBD), Feb:30-32, 34, 36-38
PIP and SPOUT signals, Jan:6-7
magnetic solution, Apr:4, 6
Tools of the Trade Catalog, Apr:65
Foreign Service
760 GLE (Volvo), failing Hall effect sensor ('88-'90), Sep:25-26
900 (Saab)
inoperative conditioning compressor, Aug:19
solving electrical glitches, Aug:16, 19
Accord (Honda)
EGR passage clogging ('90 on), Jan:18, 20
misfiring under load ('90 on), Jan:18, 20
Acura, sudden no-start/uneven cranking rhythm/vacuum, Feb:20-21
BMW
3/5-Series, corroded harness connector ('88 on), Oct:17
electrical problems, Oct:14, 17
Camry (Toyota), may not start in wet weather ('87-'91), Jul:22, 25
correction to August **Foreign Service,** Oct:17
Honda, sudden no-start/uneven cranking rhythm/vacuum, Feb:20-21
removing deposits from EGR passages in Japanese engines, May:24, 27
Snake-Bit, EGR passage cleaner, May:27
tips on replacing Japanese distributor caps, Jun:22, 25
Toyota
throttle position sensors, Mar:22, 24, Apr:14, 17
truck, may not start in wet weather ('90 on), Jul:22, 25
vane airflow sensors, Nov:22, 24, 27, Dec:16, 19
Vetronix Corp., Mastertech software update for Toyota and Honda, Dec:19
Volvo
200-Series, deteriorated wiring insulation ('80 on), Sep:22, 24
700-Series, deteriorated wiring insulation ('80 on), Sep:22, 24
700-Series, pump relay and crank sensor trouble ('88-'91), Sep:25
wet-weather driveability symptoms on dry days, Sep:26
Forester (Subaru), new sport utility vehicle, Aug:53
Four Seasons, refrigerant flushing gun, Apr:44
Fox (Volkswagen)
1.8-liter, erratic idle ('89), Nov:96
loud fuel injectors ('91-'93), May:113
rear tire wear, Jun:61-62
FRAM, first annual Food Drive, May:105
Franchising
Franchise Handbook, Jan:28
Franchise Opportunities Guide, Jan:28
International Franchise Association (IFA), web site address, Jan:28
FREEZONE, RB-276 coolant, Jan:49
Freudenberg-NOK, agreement with DuPont for Vespel parts, Nov:100
F.Y.I.
200SX (Nissan), expanded line of remanufactured transmissions, Jun:64
240 (Volvo), a/c retrofit kit, Jun:64
700-Series (Volvo), a/c retrofit kit, Jun:64
940 (Volvo), a/c retrofit kit, Jun:64
AAA Foundation for Traffic Safety, *The Older and Wiser Driver* video, Mar:75
AAMCO, oldest brake lathe contest, Jun:64
Accomatic Transmission Parts, new catalog available, Dec:61
ACDelco
air conditioning deodorizer, Nov:100
new line of remanufactured rack and pinion steering gear, Apr:59
Advantage Lift Systems
acquisition of Globe Lift Co., Jul:66
environmental low volume retrofits for in-ground lifts, Sep:86
AE Clevite Engine Parts, "Think" Campaign, Aug:67
ALLDATA, web site address, Apr:59
Altima (Nissan), expanded line of remanufactured transmissions, Jun:64
ASE
International Automotive Technician's Network (iATN), web site address, Apr:59
Testing schedule, Mar:75, Sep:86
Association of Automotive Aftermarket Distributors, name change, Jan:49
Association of Diesel Specialists (ADS), TechCert Technician Recognition Awards, Jan:49
ATP, lockup converter delay harnesses, Sep:88
Auto Shop-Aid, transmission fluid recovery system, Sep:90
Auto Value Associates, scholarships available, Jul:66
Automotive Aftermarket Industry Week, Mar:75
AAIW Interactive Show Directory database, Aug:67
Automotive Parts and Accessories Association (APAA), creation of scholarship program, May:117
Automotive Parts Rebuilders Association (APRA)
1997 Membership Directory, Jul:66
Five Ways or More to Make the Best Use of Your Time video, Feb:59
How to Get Customers, Keep Customers and Profit from Endless Referrals video, Feb:59
ISO 9000: The Good, the Bad and the Ugly video, Feb:59

1997 Motor Magazine Index

The Internet: How to Market Your Product and Company video, Feb:59
The Secret of Managing and Motivating Today's Demanding Workforce video, Feb:59
Automotive Service Association (ASA)
A Guide to the 105th U.S. Congress, Sep:86
School-to-Work Educational Resource Guide, May:117
web site address, Sep:86
Automotive Service Association Management Institute (ASAMI)
approves S.M.A.R.T. program, Jun:64
Emil Stanley Merit Award recipients, Feb:59
Hiring the Superstars! self study course, Dec:61
Managing Your Business for Profit self study course, Dec:61
Automotive Warehouse Distributors Association (AWDA), creation of scholarship program, May:117
Bars Leaks, three new stop-leak and conditioner products, Aug:67
Beck/Arnley Worldparts Corp.
1996 New Clutch Sets catalog, May:117, Dec:61
1996 Rotating Electrical Products, Apr:59
import starters and alternators poster, Mar:75
Black Gold Corp., waste oil fired boiler, Jan:49, Aug:67
BMW of North America, Service Technician Education Program (S.T.E.P.), Aug:67
Bryco, Toyota A340F filter and filter kit available, Dec:61
CARQUEST Excellence Award recipient, May:117
CCar-*Green*Link, receive Hammer Award, May:117
Centrum, PHD hardware device for Internet access, Sep:86
Century Manufacturing, acquires P&F Technologies, Aug:67
Childs and Albert, engine performance parts catalog, Dec:61
Clayton Industries, ASM dynamometer meets BAR requirements, Jul:66
COATS, oldest tire changer/balancer contest, Jun:64
Contact East, test equipment, tools and supplies catalogs, Jun:64, Jul:66, Oct:36
Cooper Automotive
donation to high school automotive training program, May:117
product donation, Oct:36
Cottman Transmission Systems, 35th anniversary, Mar:75
Craftsman, *Power and Hand Tools* catalog, Oct:36
Crown Remanufacturing, *Constant Velocity Driveshafts* catalog, Dec:61
Dana Corp., NASCAR oil and air filters, Jan:49
Douglas Battery, ISO 9000 certification, Feb:59
DuPont
agreement with Freudenberg-NOK for Vespel parts, Nov:100
refrigerant recovery and recycling agreements, Mar:75, Aug:67
DuPont Suva Refrigerants, training seminars, Jul:66
DynoMax Performance Exhausts, new line of high-performance mufflers, Feb:59
Earl's Performance Products, Hyperfirm brake lines, Sep:90
Enginetech, valve stem seal identification chart, Nov:100
Envirotech Systems, four private label automotive refrigerants, Apr:59
Equipment and Tool Institute (ETI), *1997 Member Training Directory,* Nov:100
Everco Temperature Control Products
1997 Master Temperature Control catalog, Jun:64
A/C Retrofit Manual, Apr:59
Power Steering Pumps and Gears Catalog, Jan:49
Federal-Mogul
National Redi-Seal program, Aug:67
Sealed Power Engine and Transmission Mounts, Jan:49
Fel-Pro Inc.
1997 Master Gasket Catalog, Nov:100
1997 Medium and Heavy Duty Truck and Tractor catalog, Dec:61
Automotive Technicians Scholarship Program awards, Jan:49
crush-resistant head gasket for Honda, Apr:59
new head gasket for Chevy small block engines, May:117
Tech Network brochure, Mar:75
Fluke Corp., new multimeter warranty, Feb:59
Fluoro Tech, refrigerant recovery and recycling agreement with DuPont, Mar:75
Ford, high-temp head gasket, Mar:76, 78
Freudenberg-NOK, agreement with DuPont for Vespel parts, Nov:100
G20 (Infiniti), expanded line of remanufactured transmissions, Jun:64
Gabriel Ride Control Products, discounts on Branick strut spring compressor, Dec:61
Gent-l-kleen Products, Ultra Power Wipes, Sep:89, Oct:B21
GO/DAN Industries
1997 radiator and heater core catalog, Nov:100
Air Conditioning Condenser catalog, Oct:B21, 36
GOJO, Hand Medic cream, Aug:67
Hannay Reels, cable reel catalog, Jan:49
Hastings Filters, expanded product line, Jan:49
H.C. Protek, newly developed test instruments, Nov:100
Heli-Coil, repair kit catalog, Oct:36
Helping Emergency Liaison Personnel (H.E.L.P.), glove box emergency packet, Jul:66
Hewlett-Packard, strategic alliance with SPX Corp., May:117
I30 (Infiniti), expanded line of remanufactured transmissions, Jun:64
Ingersoll-Rand, clothing and accessory catalog, Apr:59
Institute of Materials, motor oil comparison test results, Jul:66
International Copper Association, CuproBraze copper-brass radiators, Aug:67
International Engine Technology
exhibitor at SEMA/AI show, Nov:100
remanufactured Japanese engine catalog, Dec:61
International Mobile Air Conditioning Association (IMACA), retrofit guides, Oct:36
ITT Automotive Aftermarket
brake shoe and disc pad catalog, Mar:75
sale of, Nov:100
John Bean Co., merge with Snap-on/Sun, Jul:66
Johnson Industries, refrigerant agreement with DuPont, Aug:67
Lucas Aftermarket Operations
1997 Remanufactured Alternators, Starters and Generators, Mar:75
Brakes and Clutches catalog, Mar:75
Mac Tools, form network with SPX Corp's Automotive Diagnostics division, Feb:59
Management Information Systems Group, *EDI Directory of Aftermarket Suppliers,* Jun:64
Marquette, welder and welding products catalog, Mar:75
Maxima (Nissan), expanded line of remanufactured transmissions, Jun:64
Melling Automotive Products, web site address, May:117
Mighty Auto Parts, brake service poster, Jun:64
Mobil Oil, Mobil 1 Extreme Formula OW-30 synthetic oil, Feb:59, Mar:75
Mobile Air Conditioning Society (MACS)
convention and trade show, Jun:64
honored by EPA, Nov:100
training seminars, Jul:66
Monroe Shock Absorbers, Big A Auto Parts 1996 Vendor of the Year, Dec:61
Moog Automotive
K6483 Problem Solver idler arm, Sep:88
new incentives, Jul:66
World Training Center, Oct:36
Mopar, *Factory Engineered Performance Parts* catalog, Apr:59, Jul:66
Motor and Equipment Manufacturers Association (MEMA), creation of scholarship program, May:117
Mr. Gasket
Performance Group, DeskTop DragStrip engine building simulation software, Jul:66
Performance Parts and Custom Accessories, Jan:49
Murray Temperature Control, R-12 conversion tool catalog, Aug:67
NAPA Institute of Automotive Technology (NIAT), *Understanding Automotive Electrical/Electronics* self study program, Feb:59
NAPA United Application Engineered, D_2EA certified friction Products, Apr:59
NAPA/ASE, Technician of the year, Jun:64
NATEF, *Alternative Fuels Vehicle Technician* training video, Oct:36
Navistar International Transportation, 1996 Automotive Training Managers Council Excellence Award, Jul:66
NEBS Inc., Form Magic software, May:117
OTC, 180-page tool and equipment catalog, Sep:86
Overseas Automotive Council (OAC), scholarship programs, Oct:36
Perfect Circle, Machinist of the Year Award, Mar:75, Aug:67
Pioneer, *Transmission Parts* catalog, Nov:100
PitLane Products, US importer of Beta Tools, Oct:36
Powerhouse Products, dial bore gauge, Sep:89
Precision Universal Joint, T-40192-1 U-Joint service tool, Sep:89
Products Research Inc., SPX/OTC exclusive marketer and distributor, Dec:61
Quaker State Corp., FREEZONE RB-276 coolant, Jan:49
Quest (Nissan), expanded line of remanufactured transmissions, Jun:64
Quick Quote, estimating software package, May:117
R&B
Dorman full-line suspension mount program, Sep:86
Mighty Clear wiper blade replacements, Jul:66
Raybestos Brakes
brake and safety center incentive packages, Jun:64
D_2EA certified brake pads, Jan:49
introduce NASCAR apparel and gifts, Aug:67
Refrigerant Gases, FREEZONE RB-276 coolant, Jan:49
ROL Gaskets, new line of performance gaskets, Feb:59
Rotary Lift
2-post Surface Lift Brochure, Sep:86
Heavy Duty Lift Program Guide, Jul:66
Senate Productivity Award, Apr:59
SL9-Smart Lift Interactive CD, Jul:66
Rotor Clip, tool brochure, Dec:61
Safety-Kleen, collection program for used oil filters/waste gasoline, Feb:59, Sep:86
Sentra (Nissan), expanded line of remanufactured transmissions, Jun:64
Service Technicians Society (STS), 1000th member honored, Jan:49
SK Hand Tool, 75th anniversary tool catalog, Nov:100
Snap-on Tools
CDR20 cordless driver/drill, Sep:88
named premier home-based franchise, Dec:61
Snap-on/Sun, merge with John Bean Co., Jul:66
Society of Automotive Engineers
Automotive Air-Conditioning Refrigerant Service Guide, May:117
On-Board Diagnostics for Light and Medium Duty Vehicles Standards Manual, Apr:59
SPX Corp.
Automotive Diagnostics division forms network with Mac Tools, Feb:59
strategic alliance with Hewlett-Packard, May:117
Technical Chemical Company, Johnson's Freeze 12 refrigerant accepted by EPA SNAP program, Apr:59
Thexton Mfg., master cylinder bleeder, Sep:90
Toledo Trans-Kit, *Import Transmission Application Chart,* Jul:66
Tomco, improved mass airflow sensor, Sep:89-90
Tracer Products
Tracerline Fluoro-Lite/P leak-detection dye meets standards, Jun:64
UV-Fluorescent dye and detection equipment brochure, Oct:36
Truecraft Tools, ProMate Tools catalog revised, Dec:61
Used Oil Management Association (UOMA), name change, Jun:64
Valvoline Instant Oil Change
named top oil change franchise, Apr:59
opening in Sears, May:117
Van Norman, V22 combination brake lathe, Sep:88
Victor Reinz, *Performance Gasket* catalog, Jun:64
Volvo, *Pre Owned Volvo Accessory Guide,* Feb:59
Wagner Brake Products, introduces three new brake parts assortments, Sep:86
WD-40 Co., introduces T.A.L. (Triple Additive Lubricant), Feb:59
Weld-Light Distributing, welding aid, Sep:88
Wells Mfg., *Counter Point* newsletter, Nov:100

G

G20 (Infiniti)
ABS light on ('91-'93), Oct:30
blue smoke and/or excess oil consumption ('91), Mar:65, 67
expanded line of remanufactured transmissions, Jun:64
hard cold start and rough idle ('91), Feb:50
G20/G30 truck (GM), 7.4-liter, low power/overheating ('90-'93), Oct.28-29
G-Series truck (GM)
4.3-liter, sustained detonation ('92), Mar:65
van, 5.7-liter, cold sag/hesitation/sulfur smell ('93), May:114

Gabriel Ride Control Products, discounts on Branick strut spring compressor, Dec:61
Galant (Mitsubishi)
noisy a/c operation ('94-'95), Apr:58
SOHC engine, timing belt noise ('89), Mar:67
Gates, timing belt replacement manual, Sep:91
General Motors Corp., *See also specific models*
2.8/3.1/3.8-liter, start and stall and/or multiple driveability problems, Mar:40
2500-Series truck, 6.2-liter, special scan tool required, Oct:20
advanced engine systems, Mar:64
cooling fan schematics, Aug:36
counterfeit parts, Jan:44
defective solder joints in computers, Feb:19
Fuel Trim, Feb:37-38
Goodwrench Service Plus program going nationwide, Nov:88-89
inoperative MIL testing procedure update, Feb:52
new head gaskets for Chevy small block engines, May:117
On-board Diagnostics System (OBD), Feb:30-32, 34, 36-38
tips for scoping out of the way electronic components, Aug:6, 8
truck
knocking noise in engine, Apr:8, 10, 12
V6, jumps into open loop at idle, Mar:40
W-cars 3.4-liter DOHC, slight surge during extended deceleration ('91-'93), Apr:57-58
stall hot or cold ('91-'92), Apr:57-58
w/center takeoff steering racks, improper tie-rod installation, Oct:24
w/CS-Series alternators, erratic engine performance, Mar:36
w/distributorless ignition, no spark on two companion cylinders, Mar:37-38
General Motors Service Parts Operations (SPO), counterfeit parts, Jan:44
Gent-l-kleen Products, Ultra Power Wipes, Sep:89, Oct:B21
George Johnson Products, Wrench Selector Tool, Aug:72
GL (Subaru), inoperative heater ('89), Dec:58
Global Automotive Image Survey results, Jul:59
Global Positioning Systems (GPS)
Acura 3.5RL, Aug:14-15
navigation system on the SSC concept vehicle, Jan:15
Global Test Systems
fraud, Jul:82
Universal Testing Equipment new name, May:96
Glove Boy, latex work gloves, Jan:50
GO/DAN Industries
1997 radiator and heater core catalog, Nov:100
Air Conditioning Condenser catalog, Oct:B21, 36
GOJO Industries
Hand Medic cream, Aug:67
high-tech hand care research, Dec:47-48
Golf (Volkswagen)
rattling noise at front brakes ('90-'91), Mar:1
rear tire wear ('93 and older), Jun:61-62
release bearing replacement ('80-'93), Jun:36
starter won't engage ('89-'90), Aug:62
w/cruise control, brake dragging and noise ('94), Mar:1
Goodall Manufacturing Co., combustion leak tester, Jul:48
Goodyear, Gatorback Poly-V and V-belts, Apr:65, Jul:75
GPS. *See* Global Positioning Systems (GPS)
Grand Am (Pontiac)
2.3-liter, TCC chuggle ('93), Dec:50
longer-life brake pads ('91-'95), Jun:61, Aug:63
rear brake drag ('95), Aug:59
rough running/hesitation/tightly routed engine harness ('94), Feb:48
Grand Cherokee (Jeep)
2.5/4.0-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
5.2-liter
revised viscous fan clutch ('93), Oct:31
rough idle, miss and/or hard or no-start ('94-'95), Mar:65
brakes, rattle in rear wheel ('94), Jan:1
Grand Marquis (Mercury)
4.6-liter
MIL blinking/DTC P1408 in memory ('94), Dec:10, 12-13
rough idle, miss, stumble ('91-'92), Jul:60
brake roughness ('82-'95), Aug:65-66
erratic shifting ('92-'95), Mar:70
ignition module connector change ('94 on), Nov:93
Grand Prix (Pontiac)
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
brake noise, high pedal effort, decreased pad life ('88-'93), May:1
new V6 engine ('98), Sep:55-56
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Grand Wagoneer (Jeep), 5.2-liter, revised viscous fan clutch ('93), Oct:31
GS (Lexus), 1998 tech report, Dec:23, 26

H

Hannay Reels
cable reel catalog, Jan:49
web site address, Jun:64
Hastings Filters, expanded product line, Jan:49
H.C. Protek
D688 automotive digital multimeter, Nov:104
newly developed test instruments catalog, Nov:100
Hein-Werner, Blackhawk MultiBench Lift, Nov:104
Heli-Coil, repair kit catalog, Oct:36
Helping Emergency Liaison Personnel (H.E.L.P.), glove box emergency packet, Jul:66
Hennessey Industries
AMMCO Model 2800 Environmental Lathe Enclosure, Jun:65
web site address, Mar:75
Hewlett-Packard, strategic alliance with SPX Corp., May:117
Hickok Inc., New Generation STAR (NGS) tester, Oct:B21
Hombre (Isuzu), false ABS DTCs 35, 36 and 37 ('96), Mar:1
Honda, *See also specific models*
1.8-liter, oil in the coolant ('84), Sep:84
ABS rear wheel speed sensor harnesses reversed ('97), Sep:1
American Honda's Dealers Service Center, Jan:43-44
sudden no-start/uneven cranking rhythm/vacuum, Feb:20-21
Hotlines
Filter Manufacturers Council (FMC), used filter hotline, Jan:44
Standard Plus Club, driveability hotline, Mar:36-40, Jun:78
Volvo, National Technical Hotline, Jun:64
Wagner Brake Products, brake service hotline, Jun:16-17
Hydra-Lift
Model 88 Open Beam general service lift, Jan:50
Model 900 Alignment Lift, Mar:78
Hyundai, *See also specific models*
DTC11 and poor driveability, Oct:30
hard starting, Dec:58

I

I30 (Infiniti), expanded line of remanufactured transmissions, Jun:64
I-Tech Engines, reman engines, Sep:91
I/M testing, future of, Jan:39
IATN. *See* International Automotive Technicians' Network (iATN)
ICI Klea, web site address, May:117
Ideal Div. of Stant, 52F Series fuel injection hose clamps, Mar:79
Identifix, wiring diagrams by fax, Nov:103
IFA. *See* International Franchise Association (IFA)
Imperial (Chrysler), 3.3/3.8-liter, serpentine belt noise ('91-1/2-'93), Aug:59
Impreza (Subaru), no a/c ('93), May:113
Indy Racing League (IRL)
Aurora V8 engine and chassis update, May:30-32, 33-34
Championship Association of Mechanics (CAM), May:102
Inficon, TEK-Mate, heated diode leak detectors, Apr:41-42
Ingersoll-Rand
air powered die grinders, Mar:78
clothing and accessory catalog, Apr:59
Injectors, diagnosing with scope, Feb:26, 28
Innova Electronics, 3500 Series timing lights, Dec:62
Institute of Materials, motor oil comparison test results, Jul:66
Insurance Institute for Highway Safety, approve air bag deactivation, Jul:58-59
Integra (Acura)
GS-R/LS, ABS light on with DTC1 ('94), Oct:32
no upshift ('86-'89), Mar:74
notchy clutch pedal feel ('90), Mar:68
resetting the Maintenance Reminder Lamp (MRL) ('94-'97), Jun:44
Intelligent Transportation System (ITS)
National Awareness Campaign, Apr:47
Transportation Research Board (TRB), smart roads campaign, Mar:64
Interactive Satellite Career Fair, Coordinating Committee for Automotive Repair (CCAR), Jul:56, 58
International Automotive Technicians' Network (iATN), web site address, Apr:2, 59, Oct:22, Nov:40
International Copper Association, CuproBraze copper-brass radiators, Aug:67
International Engine Technology exhibitor at SEMA/AI show, Nov:100
remanufactured Japanese engine catalog, Dec:61
International Franchise Association (IFA), web site address, Jan:28
International Lubricants
Dr. Tranny's Assemblee Goo, Aug:72
LUBEGARD ATF protectant, Aug:73
LUBEGARD engine protectant, Oct:B22
LUBEGARD limited slip supplement, Nov:104
LUBEGARD power steering protectant, Sep:92
Standardization and Approval Committee (ILSAC), requirements for new oil classifications, Apr:49
International Mobile Air Conditioning Association (IMACA), retrofit guides, Oct:36
Internet, *See also* World Wide Web (WWW)
Centrum, PHD hardware device for Internet access, Sep:86
Putting the Internet to Work for You, Nov:38-40
Interro Systems
ECVu ECM Analyzer, Sep:36, 38
OBDII scan tool, Oct:B22, Dec:64
Intrepid (Dodge)
3.5-liter, buck and/or miss at cruising speed ('93), Feb:52
ABS light on intermittently ('93), Jan:1
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
new V6 engine ('98), Sep:55-56
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Intrigue (GM), new V6 engine ('98), Sep:55-56
IRL. *See* Indy Racing League (IRL)
Isuzu, *See also specific models*
2.3-liter, cracked head, Jul:48
pickup
2.3-liter, high idle ('89-'90), Feb:51-52
2.6-liter, hard starting, fuel pump problems ('89-'90), Mar:70
high idle ('89-'91), Jan:47
ITS. *See* Intelligent Transportation System (ITS)
ITT Automotive Aftermarket
brake shoe and disc pad catalog, Mar:75
sale of North American division, Nov:100

J

J30 (Infiniti)
cell phone interference ('93), Jun:57
climate control blows hot humid air ('93), Apr:55
J.A. Echols and Associates, HeCat FAC 500 Flush 'N' Cycle a/c flushing machine, Apr:46, Jul:68
Jaguar, *See also specific models*
sedan
3.6-liter, engine pinging ('89), Dec:57-58
EGR problems ('90), Jan:48
engine run-on ('90), Aug:62
Jendham, *OBDII Quick Reference Guide*, May:118, Dec:62
Jetta (Volkswagen)
rattling noise at front brakes ('90-'91), Mar:1
rear tire wear ('93 and older), Jun:61-62
release bearing replacement ('89-'93), Jun:36
starter won't engage ('89-'90), Aug:62
w/cruise control, brake dragging and noise ('94), Mar:1
Jimmy (GMC), 4.3-liter, natural gas conversion, engine replacement, May:14, 16, 19
John Bean Company
CAS shop management system, Oct:B22
sonic technology wheel balancer, Oct:B22
Visualiner 3D wheel alignment system, Sep:46-47, Oct:B22
JohnDow Industries, mobile oil drain, Jun:66
Johnson Controls, Thin Metal Foil battery, Dec:44, 46-47
Johnson Industries, refrigerant agreement with DuPont, Aug:67

K

K&W Products, Knock'er Loose penetrant, Oct:B22
Kaeser Compressors, AMD-6550 automatic compressed-air drain, Jul:69
Kal Equipment, KalScope, Mar:80, May:125, Oct:B22
Kano Laboratories, SiliKroil penetrant/lubricant, Aug:72
Kastar Hand Tools
15 piece metric thread restore kit, Nov:104
GM W-Car rear guide pin removal tool, Feb:61
Master power steering pump/alternator pulley remover/installer kit, Nov:98
Master spindle rethreader die set, Feb:65, May:119
oil drain plug wrench set, Jan:50
web site address, Mar:75
Katech Menard, new Aurora V8 engine, May:32
Kent-Moore
black light and trace dye crack detector, Jul:48
GM Mid-year Special Service Tools catalog, Sep:91
wiring harness repair kit, Nov:104

L

L&S Automotive, precision antifriction bearings, Jul:70, Dec:64

1997 Motor Magazine Index

Lanair, waste oil heater, Jan:53, Feb:62, Sep:92, Nov:104
Landa
  PDX Series portable cold-water pressure washers, Mar:75
  Spin Jet automatic parts washer, Apr:60-61
Landau (Chrysler), 3.0-liter, cold hesitation, DTC13 ('89), Mar:68
Lathem Time Corp., 5000E multifunction time clock, Apr:60
LeBaron (Chrysler), 3.0-liter, rough idle, stall, hesitation ('90), Mar:67
Legacy (Subaru), DTC32 in memory/no symptoms, Jun:62-63
Legend (Acura)
  coupe, metallic knock when cold ('91-'92), May:114-115
  inaccurate speedometer reading ('91), Jul:63-64
  no upshift ('86-'93), Mar:74
  overflowing brake fluid ('89), Sep:80
  sedan, metallic knock when cold ('91-'93), May:114-115
LeSabre (Buick)
  3800 V6
    revised engine torque specs ('92-'95), Jun:62
    service manual update, Kent-Moore tool not needed ('93), Apr:52
    service manual update, YES/NO boxes reversed ('93-'95), Jul:65
  buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
  starter motor change ('95), Sep:84
Lexus, *See also specific models*
  modified overdrive clutch bearing, May:116
LHS (Chrysler)
  clicking in front end ('93-'95), Sep:82
  front brake service recommendations ('93-'95), Jul:63
Lincoln
  Banner B67597 high-lift transmission jack, Mar:78
  Model 3653 antifreeze drain, Aug:68
  new bottle jacks, Jun:65
Lisle
  antenna nut socket set, Feb:61
  Model 43800 cam-lock puller, Mar:76
  Model 50750 oil filter pliers, May:118
Lista international, mobile work stations, Feb:60
Littelfuse Aftermarket Products, web site address, Mar:75
Loyale (Subaru), white smoke while turning right ('90 and older), Aug:62
LS400 (Lexus)
  1998 tech report, Dec:23, 26
  groaning noise after engine is shut down ('91), Aug:62
LSS (GM), buzz/rattle from instrument panel when brake pedal is depressed ('96-'97), Sep:1
Lucas Aftermarket Operations
  1997 Remanufactured Alternators, Starters and Generators catalog, Mar:75
  Brakes and Clutches catalog, Mar:75
Lumina (Chevrolet)
  3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
  3.8-liter, gradual power loss ('93-'95), Feb:52
  3800 V6
    revised engine torque specs ('92-'95), Jun:62
    service manual update, Kent-Moore tool not needed ('93), Apr:52
    service manual update, YES/NO boxes reversed ('94-'95), Jul:65
  brake noise, high pedal effort, decreased pad life ('90-'93), May:1
  fuel tank noise ('90-'95), Mar:73
  new design tie rod end ('93-'95), May:119
  Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Lynx (Mercury)
  1.9-liter, buck and/or jerk at highway speed ('86-'90), May:116
  brake roughness ('82-'87), Aug:65-66

M

M3 (BMW)
  electrical problems ('93), Nov:97
  engine run-on/rough idle ('89), Sep:84
M30 (Infiniti), grinding brakes ('90), Nov:93
M/L-Series truck (GM), 4.3-liter, sustained detonation ('92), Mar:65
Mac Tools Inc.
  ET18DMM digital multimeter, Jun:67
  ET2010 Lab Scope, Sep:44, 46
  forms network with SPX Corp's Automotive Diagnostics division, Feb:59
  MacWave diagnostic tool, Oct:B23, Dec:64
MACS. *See* Mobile Air Conditioning Society (MACS)
MAK Industries, Versapulr pulling tool, Feb:60, Sep:42
Management Information Systems Group, web site address, Jun:64, Oct:36
MAP. *See* Motorists Assurance Maintenance Program (MAP)
MARCSTAR. *See* Multi-channel Advanced Remote Control Serial Data Transmitter and Receiver (MARCSTAR)
Mark VII (Lincoln), brake roughness ('84-'92), Aug:65-66
Mark VIII (Lincoln)
  brake roughness ('93-'95), Aug:65-66
  hard cold start ('93-'95), Nov:96
  ignition module connector change ('94 on), Nov:93
Marquette
  Amp Champ 12-volt power supply, Nov:99
  welder and welding products catalog, Mar:75
Maserati, 3-liter, rough idle, stall, hesitation ('90), Mar:67
Matco Tools, MT1832 3/8" wobble drive air ratchet, Sep:44
Maxima (Nissan)
  expanded line of remanufactured transmissions, Jun:64
  fan runs continuously ('89-'90), Dec:58
Maxwell Dynamometer Systems Inc., emission testing equipment, Mar:80
MEA. *See* Mechanics' Education Association (MEA)
Mechanics' Education Association (MEA), collecting proprietary information, Oct:20, 22
Melling Automotive Products, web site address, May:117
MEMA. *See* Motor and Equipment Manufacturers Association (MEMA)
Mercedes-Benz, *See also specific models*
  124-chassis
    exhaust noise ('90-'91), Aug:64
    faulty cruise control ('89-'90), Feb:51
  126/201-chassis, faulty cruise control ('89-'90), Feb:51
  300-Series, exhaust noise ('90-'91), Aug:64
  A-Class, micro car introduced ('98), Feb:56
  electronic brake assist system ('98), Jul:56
  hard start/noisy timing case, Dec:58
  M102/103 engine, ballooned torque converter, Aug:66
  M-Class, all-activity vehicle introduced ('98), May:110
  oil leaks, Nov:94
  ParktronLic system, Sep:70
  resetting the Oxygen Sensor Maintenance Reminder Lamp/removing the bulb, Jun:47
Mercur (Mercury)
  Scorpio, brake roughness ('88-'89), Aug:65-66
  XR4Ti, brake roughness ('85-'88), Aug:65-66
Metro (Geo)
  1-liter
    cylinder head oil restrictor ('89-'95), May:116
    service manual update/checking ECR pressure tranducer ('89-'94), May:114
Micro Processor Systems Inc. (MPSI), web site address, Oct:36
Micromate Manufacturing, high-accuracy bore gauges, May:118
Midtronics, PowerSensor Micro400 digital battery analyzer, Sep:42, 44, Oct:B23
Mighty Auto Parts, brake service poster, Jun:64
Miller Electric Mfg.
  Millermatic Challenger MIG welder, Jun:66
  web site address, Sep:86
Mirage LS (Mitsubishi), tire rubbing ('90), Aug:64
Mister Nut, Ford spring lock coupler repair kit, Jul:68
Mitchell Repair, CD-ROM transmission repair information, Nov:104
Mitsubishi, *See also specific models*
  2.6-liter
    cracked head, Jul:48
    shaft bearings leaking oil, Jul:47
  introduces In-cylinder Gasoline Direct Injection (GDI) engine, Apr:50-51
  resetting the Maintenance Required Lamp (MRL)/removing the bulb, Jun:47
  SOHC engine, timing belt noise, Mar:67
Mitsubishi Motor Sales of America Inc. (MMSA), enters Canadian market, Apr:47-48
ML320 (Mercedes-Benz), new sport utility vehicle, Aug:52
Mobil Oil, Mobil 1 Extreme Formula OW-30 synthetic oil, Feb:59, Mar:75
Mobile Air Conditioning Society (MACS)
  contaminated and blend refrigerants, Apr:22-24, 27-28
  convention and trade show, Jun:64
  honored by Environmental Protection Agency, Nov:100
  retrofit service tips, Apr:30-31, 34, 36-38
  tests of blends in passenger cars, Apr:28
  training seminars, Jul:66
  web site address, Jul:66, Nov:40
Mohawk Resources Ltd.
  TP-30 surface mount lift, Sep:88
  two post lift comparison booklet, Mar:85, Sep:91, Oct:B25
  web site address, Oct:36
Monaco (Dodge)
  3.0-liter, no start/no compression ('90-'92), Apr:52, 55
  cam plug charge ('88-'92), Sep:78
Monroe Shock Absorbers, Big A Auto Parts 1996 Vendor of the Year, Dec:61
Monte Carlo (Chevrolet), Team ASE Racing stock car, May:84, 87
Montero (Mitsubishi), Sport, update ('97), Feb:46
Moog Automotive
  K6483 Problem Solver idler arm, Sep:88
  new design tie rod end, May:119
  new incentives, Jul:66
  Windstar (Ford), rear cargo springs ('95 on), Apr:62
  World Training Center, Oct:36
Mopar Performance, *Factory Engineered Performance Parts* catalog, Apr:59, Jul:66
Mosan Corp., ICOR Hot Shot refrigerant, Mar:80, Jun:71
Motor and Equipment Manufacturers Association (MEMA), creation of scholarship program, May:117
MOTOR Information System, MOTOR Publication's new name, Jun:51-52
Motor Life Distributors, Bilstein R-2000 Engine Flush System, Mar:76
MOTOR Magazine
  back issues, Feb:65, May:125, Jun:71, Jul:75, Aug:73, Sep:95, Nov:107
  fraudulent use of name by Universal Testing Equipment, May:89-90
  Service Slants on disk, Jun:71, Aug:73, Sep:95, Nov:107, Dec:64
  Top Twenty Tools, Sep:34-48
  web site index, Jan:60
MOTOR Magazine/ASA, 1997 Automobile Technician of the Year, Dec:44
MOTOR Publications
  agreement with ALLDATA, Jan:40
  Labor Time Guide, Oct:12-13
  name changed to MOTOR Information System, Jun:51-52
MOTOR/ALLDATA Systems, agreement between MOTOR Magazine and ALLDATA, Jan:40
Motorist Assurance Maintenance Program (MAP)
  developing guidelines and standards for auto maintenance, Jul:2
  How to Find Your Way Under the Hood and Around the Car brochure, Jul:2
  safety inspections, standards of service, May:98
  web site address, Nov:40
Mountaineer (Mercury), update ('97), Feb:45
MPSI
  Pro-Link OBDII cartridge, Oct:B23
  Spectra-Gas gas analyzer, Nov:104
MPV (Mazda)
  3.6-liter, stalls after start when cold ('88-'89), Jan:48
  ABS indicator stays on and DTC53 stored in memory, Sep:1
  resetting the Malfunction Indicator Lamp (MIL), Jun:46
Mr. Gasket
  carburetor rebuilding kit, Nov:98
  Performance Group
    DeskTop DragStrip engine building simulation software, Jul:66
    DeskTop Dyno engine building simulation software
  Performance Parts and Custom Accessories, Jan:49
  web site address, Jul:66
Multi-channel Advanced Remote Control Serial Data Transmitter and Receiver (MARCSTAR), introduced, Jan:40
Murray Temperature Control, R-12 conversion tool catalog, Aug:67
Mustang (Ford)
  5.0-liter, tip-in stumble 30 seconds after hot soak ('88), Jul:63
  adjustable strut mounts ('79-'93), Apr:62
  brake roughness ('92-'95), Aug:65-66
  ignition module connector change ('94 on), Nov:93
  rear disc brake squeak ('94-'95), Oct:31
  Team ASE Racing, May:85, 87
MX-6 (Mazda), idle hunting ('89), Aug:62
Mystique (Mercury)
  brake roughness ('95), Aug:65-66
  EGR valve eliminated ('98), Sep:52, 54

N

NAC Engines, new Aurora V8 engine, May:32
NADA. *See* National Auto Dealers Association (NADA)
NAPA Institute of Automotive Technology (NIAT)
  Subscription Program self-study technical training, Jun:68
  Understanding Automotive Electrical/Electronics self-study program, Feb:59
NAPA. *See* National Automotive Parts Association (NAPA)
NASCAR
  line of oil and air filters, Jan:49
  select battery, May:125, Jul:70, Sep:91, Nov:107, Dec:63
NATEF. *See* National Automotive Technicians Education Foundation (NATEF)
National Auto Dealers Association (NADA), liability of deactivating air bags, Mar:4
National Automotive Parts Association (NAPA)
  1991-98 Imported New Car Warranty chart, Dec:64
  1998 Domestic New Car and Truck Warranties chart, Sep:95
  D_3EA certified friction products,

Apr:59
Honest campaign, Apr:47
NASCAR Select battery, May:125, Jul:70, Sep:91, Nov:107, Dec:63
NIAT subscription program self-study program, Aug:74
Technician of the Year, Jun:64
National Automotive Technicians Education Foundation (NATEF)
Alternative Fuels Vehicle Technician training video, Oct:36
Continuing Automotive Service Education (CASE), Feb:4
National Highway Traffic and Safety Administration (NHTSA)
ASA reaction to air bag proposal, Jan:40, 43
deactivating air bags, Mar:4
researching field problems with Ford IAR alternators ('84-'94), Jul:28-29
National Institute for Automotive Service Excellence (ASE)
25th anniversary, Feb:55-56
Auto Value Associates Inc., 1000 prepaid test registrations, Apr:49-50
car buying decision survey results, Nov:91
Continuing Automotive Service Education (CASE), Feb:4
good/bad customer survey results, Sep:70
oil and filter change survey results, Aug:50
Team ASE Racing, May:84-87
Crown Victoria (Ford) funny car, May:85, 87
F-150 (Ford), NASCAR Craftsman Truck Series, May:84, 86
go-kart, May:84
Monte Carlo (Chevrolet) stock car, May:84, 87
Mustang (Ford), May:84, 87
Technician of the Year, Jun:64
technicians' influence in product purchasing survey results, Nov:89-90
testing schedule, Sep:86
web site address, Nov:39
National Quick Start Sales, Iceberg Alternator, Aug:68
National Transportation Safety Board (NTSB), crash recorders in new cars, Aug:54
Navigator (Mercury), update ('97), Feb:45
Navistar International Transportation
hybrid electric concept trucks and buses, Dec:48
receive 1996 Automotive Training Managers Council Excellence Award, Jul:66
NEBS Inc.
automotive forms catalog, Feb:62, Mar:80, May:125, Jun:68
Form Magic software, May:117
Neon (Dodge/Plymouth)
2.0-liter, engine miss ('95-'96), May:113
brake growl ('95), Feb:48
electrical glitches, Jun:62
engine races during shifts ('95), Feb:50
front coil spring part numbers and spring tag ID numbers, Mar:65
front suspension noise ('95), Mar:65
loud fuel pump ('95), May:114
poor defogging ('95), Jun:57
rear brake chirp ('95-'96), Jun:1
Net. *See* Internet; World Wide Web (WWW)
Neutronics, refrigerant identifier, Apr:40-41
New Car and Truck Warranty chart, Sep:57-64
New Yorker (Chrysler)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.3/3.8-liter, serpentine belt noise ('91-1/2-'93), Aug:59
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Salon 3-liter, rough idle, stall, hesitation ('90), Mar:67
Newsbreak
Accord LX (Honda), Automated Highway System (AHS) prototype ('96), Aug:48, 50
aftermarket product sales study results, Aug:53-54, Dec:44
AlliedSignal, FRAM Food Drive, May:105
American Honda's Dealer Service Center, Jan:43-44
American Iron and Steel Institute (AISI)
developing new fuel economy technology, Jun:48, 51
Light Truck Structure study released, Jun:51
American Petroleum Institute (API), new oil classification, Apr:48-49
Auto Value Associates Inc., 1000 prepaid ASE test registrations, Apr:49-50
Automotive Information Systems Inc. (AIS), used car reliability info on CarPoint website, Sep:71-72
Automotive Service Association (ASA)
car dealer limits, Feb:56
reaction to air bag proposal, Jan:40, 43
brake exports denied to Japan, May:109
Cadillac, Radio Data System (RDS), Nov:89
California Air Resources Board (CARB)
help for aftermarket manufacturers of OBDII equipment, May:102
new emissions standards for heavy-duty diesel engines, Feb:58
CarPoint, web site address, Sep:71
Central Telephone Company (Sprint), unacceptable refrigerant use, Aug:50, 52
Championship Association of Mechanics (CAM), IndyCar crew members organization, May:102
CLK (Mercedes-Benz), Ultra Low Emissions Vehicle (ULEV), introduced ('98), May:110-111
Coordinating Committee for Automotive Repair (CCAR)
automotive education program study results, Jun:52
Interactive Satellite Career Fair, Jul:56, 58
Corvette (Chevrolet), fifth generation ('97), Feb:55
Crown Victoria NGV (Ford), first alternative fuel taxicab, Nov:90-91
customer confidence survey results, Jan:43
Dana Corp., new oil filter design, Nov:90
Delphi Saginaw Steering Systems, E-Steer electric power steering system, May:102, 105
Environmental Protection Agency (EPA)
admits error in tougher air quality standards, Jun:43
HC-12a banned, Aug:50, 52
Equipment and Tool Institute (ETI), 50th anniversary, May:108-09
EV1, technician training, Mar:56-57
EV Plus, debut, Mar:59-60
Expected Useful Vehicle Life (EUVL), study results, Jun:52
F300 (Mercedes-Benz), three wheel concept vehicle, Dec:48-49
Forester (Subaru), new sport utility vehicle, Aug:53
General Motors Corp.
advanced engine systems, Mar:64
counterfeit parts, Jan:44
Goodwrench Service Plus program going nationwide, Nov:88-89
Global Automotive Image Survey results, Jul:59
GOJO Industries, high-tech hand care research, Dec:47-48
good/bad customer survey results, Sep:70
Insurance Institute for Highway Safety, approve air bag deactivation, Jul:58-59
Intelligent Transportation System (ITS), National Awareness Campaign, Apr:47
jobber store numbers decrease, May:102
Johnson Controls, Thin Metal Foil battery, Dec:44, 46-47
Mercedes-Benz
A-Class, micro car ('98), Feb:56
electronic brake assist system ('98), Jul:56
M-Class, all-activity vehicle introduced ('98), May:110-111, Aug:52
Parktronic system, Sep:70
Mitsubishi, introduces In-cylinder Gasoline Direct Injection (GDI) engine, Apr:50-51
Mitsubishi Motor Sales of America Inc. (MMSA), enters Canadian market, Apr:47-48
Mobile Air Conditioning Society (MACS), insuring refrigerant purity, Sep:72, 77
MOTOR Information System, MOTOR Publication's new name, Jun:51-52
MOTOR Magazine/ASA 1997 Automobile Technician of the Year, Dec:44
MOTOR Publications
agreement with ALLDATA, Jan:40
name changed to MOTOR Information Systems, Jun:51-52
National Automotive Parts Association (NAPA), *Honest* campaign, Apr:44
National Highway Traffic and Safety Administration (NHTSA), air bag update, Mar:58
National Institute for Automotive Service Excellence (ASE)
25th anniversary, Feb:55-56
car buying decision survey results, Nov:91
good/bad customer survey results, Sep:70
oil and filter change survey results, Aug:50
technicians' influence in product purchasing survey results, Nov:89-90
National Transportation Safety Board (NTSB), crash recorders in new cars, Aug:54
Navistar International, hybrid electric concept trucks and buses, Dec:48
new Volvo models introduced ('98), Jun:42
number of autos in US survey results, Sep:72
NXS (Acura), 3.2-liter, review ('97), Mar:56
OBDII access lawsuit dismissed in US District Court, Nov:89
Occupational Safety and Health Administration (OSHA), citations issued for lift misuse, Aug:52-53
Pennzoil, new pure base oil, Jun:53
Pierburg AG, developing new fuel economy technology, Jun:48, 51
Prius (Toyota), hybrid gasoline/electric vehicle, Dec:48
Quaker State Corp., Slick 50 settlement, Sep:70-71
Recreational Vehicle Industry Association (RVIA), growth in RV industry, Feb:56, 58
Regal (Buick), 1997-1/2 model introduced, Jan:43
Service Technicians Society (STS), first anniversary, Apr:50
sham refrigerant retrofits, Jun:48
Snap-on Tools
new training and retail center opens, Jul:58
Tribute campaign, Apr:47
South Coast Air Quality Management District (SCAQMD), water-based cleaners regulation, Mar:60
statistics on driver ages, Mar:60
statistics on number of service stations and garages, Mar:60
stolen vehicle export statistics, Aug:54
Synergy, Feb:58
taxi driver age limit legislation defeated, Dec:48
Tenneco Automotive
Ride Expert training clinic, Jul:58
Walker Quiet-Flow muffler, Oct:B24, Nov:90
Texas Instruments
Multi-channel Advanced Remote Control Serial Data Transmitter and Receiver (MARCSTAR), Jan:40
NightDriver thermal imaging system, Jul:59
Toyota Motor Sales USA, first Toyota Customer Service Center opens, Aug:50
Transportation Research Board (TRB), ITS, smart roads campaign, Mar:64
Universal Propulsion Co., inflatable seatbelts, Sep:72
Used Oil and Oil Filter Recycling workshops, Jan:44
zero emissions vehicle ruling, Nov:90
NHTSA. *See* National Highway Traffic and Safety Administration (NHTSA)
NIAT. *See* NAPA Institute of Automotive Technology (NIAT)
Ninety Eight (Oldsmobile)
3800 V6
revised engine torque specs ('91-'94), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52
service manual update, YES/NO boxes reversed ('93-'95), Jul:65
buzz/rattle from instrument panel when brake pedal is depressed ('95-'96), Sep:1
starter motor change ('95), Sep:84
Nissan, *See also specific models*
disconnecting the Oxygen Sensor Warning Lamp ('80-'87), Jun:47
truck, transmission slippage (prior to 5/91), Mar:70, 73
Northstar (Cadillac)
4.8-liter, noisy accessory drive belt ('93-'95), Oct:24, 28
new V6 engine ('98), Sep:55-56
NTSB. *See* National Transportation Safety Board (NTSB)
NXS (Acura), 3.2-liter, review ('97), Mar:56

O

OAC. *See* Overseas Automotive Council (OAC)
OBD. *See* On-board Diagnostics System (OBD/OBDII)
OBDII. *See* On-board Diagnostics System (OBD/OBDII)
Occupational Safety and Health Administration (OSHA), citations issued for lift misuse, Aug:52-53
Oldsmobile, *See also specific models*
307-cubic inch V8
mysterious smog test failures (mid-80s), Nov:10, 12-13
smog test failure at 2500 rpm ('83-'84), May:6, 10
On-board Diagnostics System (OBD/OBDII)
access lawsuit dismissed in US District Court, Nov:89
codes, Feb:30-32, 34, 38
EGR monitoring, Feb:37
freeze frames, Feb:34
Fuel Trim, Feb:37-38
misfires, Feb:34, 36-37
OBDII Quick Reference Guide, May:118, Dec:62
On-Board Diagnostics for Light and Medium Duty Vehicles Standards Manual, Apr:59
PCM reprogramming, Feb:31
second generation, Feb:30-32, 34, 36-38
Onboard Refueling Vapor Recovery (ORVR)
problems with draining fuel tank, Sep:50-51
tech preview of the 1998 models, Sep:50-51
ORVR. *See* Onboard Refueling Vapor Recovery (ORVR)
OSHA. *See* Occupational Safety and Health Administration (OSHA)
OTC
3-in-1 fuel injection service kit, Mar:76
180-page tool and equipment

1997 Motor Magazine Index

catalog, Sep:86
exclusive Products Research Inc. marketer and distributor, Dec:61
gas analyzer diagnostic software, Feb:60
MicroGas 5-Gas Analyzer, Jul:68, Sep:34
MinuteMan portable battery tester, Jan:53, Apr:61
number 1181 multipurpose puller set, Jan:50, May:118
parasitic drain tester, Aug:70
rear axle service tool, Jun:65
Overseas Automotive Council (OAC), scholarship programs, Oct:36

P

P&F, dye injector leak detectors, Apr:41-42
Park Avenue (Buick)
3800 V6
revised engine torque specs ('91-'94), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52
service manual update, YES/NO boxes reversed ('93-'95), Jul:65
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
starter motor change ('95), Sep:84
Parts, Accessories and Supplies, *See also* Tools and Equipment; **Tools of the Trade**
ACDelco, wire and cable catalog, Apr:65, Oct:B19
Airtek Inc., CATCO catalytic converter catalog, Oct:B19
Beck/Arnley Worldparts Corp.
import engine parts, May:125
new fail-safe import thermostats, Apr:65
Pro Pack brake pad kits for imports, Jul:70
switches for imports, Jun:68
timing component;s kit, Aug:74
Berryman
brake cleaners, May:120
lubricant, Aug:73
Bryco by Carfel, timing belts and tensioners, Oct:B20
Chicago Pneumatic, higher performance improved regulator, Apr:65
Chrysler Corp., *Tech Authority* catalog, Oct:B20
Fel-Pro Inc.
Engine$aver crankshaft repair sleeves, Dec:64
Engine$aver cylinder head bolt sets, Nov:103
PermaDry Plus Gasket for Buick oil pan ('85'95), Oct:B21
SteelGard head gaskets, Sep:91
Ferodo America Inc., SpectraOne disc brake pads, May:120
Gates, timing belt replacement manual, Sep:91
Goodyear, Gatorback Poly-V and V-belts, Apr:65, Jul:75
I-Tech Engines, reman engines, Sep:91
International Lubricants
LUBEGARD ATF protectant, Aug:73
LUBEGARD limited slip supplement, Nov:104
LUBEGARD power steering protectant, Sep:92
Kent-Moore, wiring harness repair kit, Nov:104
L&S Automotive, precision antifriction bearings, Jul:70, Dec:64
Mosan Corp., ICOR Hot Shot refrigerant, Jun:71
NAPA, NASCAR select battery, May:125, Jul:70, Sep:91, Nov:107, Dec:63
NEBS Inc., automotive forms catalog, Jun:68
Raybestos Brakes
D_3EA certified brake pads, Jan:53, Mar:80, Oct:B23
Domestic and Import Brakes Parts catalog, Jun:68, Sep:91
three new product catalogs, May:125
Parts Plus
Association of Automotive Aftermarket Distributors, name change, Jan:49
web site address, Sep:86
Paseo (Toyota), erratic a/c operation ('94), Apr:56
Passat (Volkswagen)
1998 tech report, Dec:35
rear tire wear, Jun:61-62
Pathfinder (Nissan), transmission slippage (prior to 5-91), Mar:70, 73
PBR Industries, CatOil compressor/air tool oil, Aug:70
Pennzoil, new pure base oil, Jun:53
Perfect Circle
caster/camber adjusting kit, Mar:78-79
Machinist of the Year Award, Mar:75, Aug:67
Pierburg AG, developing new fuel economy technology, Jun:48, 51
Pioneer, *Transmission Parts* catalog, Nov:100
PitLane Products, US importer of Beta Tools, Oct:36
Pontiac, *See also specific models*
1.8-liter, cracked head, Jul:48
Porsche, *See also specific models*
all models, a/c leaks, May:113
Powerhouse Products
dial bore gauge, Sep:89
Holley float adjusting tool, Aug:70, 72
PowerVision Tools, undercar inspection tool, Aug:72
Precis (Mitsubishi)
hard shifting ('90), Nov:94
no-start ('90), Feb:50
Precision Feeding and Sales, Precision Crush PC100 oil filter crusher, Feb:61
Precision Universal Joint, T-40192-1 U-Joint service tool, Sep:89
Prelude (Honda)
battery drain ('89), Jan:48
drift to the right ('92-'93), Dec:57
no 1-2 upshift ('84-'92), Nov:97
Premier (Eagle)
3.0-liter, no start/no compression ('88-'92), Apr:52, 55
cam plug charge ('88-'92), Sep:78
Previa (Toyota), drone with a/c on ('91), Aug:66
PRI, Qwik-Connect test clips, Feb:61
Prius (Toyota), hybrid gasoline/electric vehicle, Dec:48
Pro-Cut International, PFM 900, hub-mounted lathe, Jun:30
Probe (Ford)
1.8-liter, hard start/hesitation/rough idle ('89-'92), Oct:29
2.2-liter
hard start/hesitation/rough idle ('89-'92), Oct:29
turbo, intermittent MIL ('90-'93), Apr:52
2.5-liter, updated connector on replacement EGR valve ('93-'94), Mar:67
brake roughness ('89-'95), Aug:65-66
hard and/or no-start ('93-'94), Aug:63
no start/hard start and Fuel Shutoff Light lit ('93-'94), May:113
Products Research Inc.
Model ISS Ignition System Simulator, Universal Testing telemarketing scam, May:88-90, 95-96
SPX/OTC exclusive marketer and distributor, Dec:61
SST III Sensor System Tester, Universal Testing telemarketing scam, May:88-90, 95-96
Universal Testing Equipment/Global Test Systems fraud, Jul:82

Q

Q45 (Infiniti), idle vibration ('90-'91), May:114, Jul:64
Quaker State Corp.
FREEZONE RB-276 coolant, Jan:49
Slick 50 settlement, Sep:70-71
Quest (Nissan), expanded line of remanufactured transmissions, Jun:64
Quick Quote, estimating software package, May:117
QX-4 (Infiniti), update ('97), Feb:46

R

R&B
Dorman full-line suspension mount program, Sep:86
Mighty Clear wiper blade replacements, Jul:66
R/V-Series truck (GM), 7.4-liter, low power/overheating ('90-'93), Oct:28-29
Ram truck (Dodge)
5.9-liter
diesel, too much oil from draft tube ('94-'95), May:116
low power, rough idle, black smoke ('94-'95), Mar:73
surge at highway speeds ('94-'95), Jan:48
8.0-liter
delayed gear engagement ('94-'95), Jun:63
low power, rough idle, black smoke ('94-'95), Mar:73
rough idle, miss and/or hard or no-start ('94-'95), Mar:65
brake drift ('94-'95), Jul:60, 63
diesel
delayed gear engagement ('94-'95), Jun:63
power loss, harsh shifts ('94), May:112-113
hard-to-shift transfer case ('94-'95), Nov:94
replacement climate control knobs ('94-'95), Apr:56
right side speakers go out when electrical accessories are used ('94), Oct:31
Range Rover, 4.0-liter, hard starting/erratic fuel gauge ('95 and earlier), Dec:57
Ranger (Ford)
4.0-liter, rear main seal tool ('90-'94), Jan:48
ignition module connector change ('94 on), Nov:93
returnless fuel injection ('98), Sep:51-52
rolling hot idle/stall ('94), May:114
update ('97), Feb:45
Raybestos Brakes
Brake and Safety Center incentive packages, Jun:64
D_3EA Certified PG Plus brake pads, Jan:49, 53, Mar:80, Oct:B23
D_3EA Certified SuperStop brake pads, Jan:49, 53, Mar:80, Oct:B23
Domestic and Import Brakes Parts catalog, Jun:68, Sep:91
introduce NASCAR apparel and gifts, Aug:67
three new product catalogs, May:125
web site address, Mar:80
Raytek, noncontact infrared thermometer, Feb:62, Jul:70, Aug:74, Dec:64
Ready Fixtures, Early Bird key drop box, Feb:62, Jul:70, Nov:107
Recreational Vehicle Industry Association (RVIA), growth in RV industry, Feb:56, 58
Refrigerants
Automotive Air-Conditioning Refrigerant Service Guide, May:117, 120
choosing a retrofit, Apr:27-28
contaminated and blend refrigerants, Apr:22-24, 27-28
destruction unit illustration, Apr:28
FREEZONE RB-276 coolant, Jan:49
illegal "drop-ins," Apr:22, 24
Johnson's Freeze 12 refrigerant accepted by EPA SNAP program, Apr:59
legal for sale blends, Apr:24, 27
Mobile Air Conditioning Society (MACS)
1997 convention discussion on, Apr:23-25, 27-28
tests of blends in passenger cars, Apr:28
recovery-only equipment, Apr:42
regulations for use of, Apr:22-24
results of tests of blends, Apr:27-28
retrofit service tips, Apr:30-31, 34, 36-38
running out of R-12, Apr:30
Regal (Buick)
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
3800 V6
revised engine torque specs ('94-'95), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52
brake noise, high pedal effort, decreased pad life ('88-'93), May:1
GS/LS introduced ('97-1/2), Jan:43
new V6 engine ('98), Sep:55-56
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
Regency (Buick), buzz/rattle from instrument panel when brake pedal is depressed ('96-'97), Sep:1
Repair systems, computerized, Jan:22-24, 25
Reznor, used motor oil furnace, Aug:73, Sep:95, Oct:B23, Nov:107, Dec:64
Riviera (Buick)
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
Robinair
Model 14780B Sentinel refrigerant identifier, Apr:40, Aug:72
Scavenger Model 17680A air-operated refrigerant recovery system, Apr:42, 60
Tracker UV leak detection system, Aug:68-70
Vacuchek, electronic vacuum gauge, Apr:42
Rocketsports, new Aurora V8 engine, May:32
Rocky (Daihatsu), resetting the Oxygen Sensor Maintenance Reminder Lamp/removing the bulb, Jun:47
Rodeo (Isuzu)
downshift clunk ('91-'93), May:116
erratic cruise control ('90-'91), Aug:62
ROL Manufacturing
Ford high-temp head gasket, Mar:76, 78
Hi-Per Blue performance valve cover gaskets, Nov:99
Rotary Lift
2-post surface lift brochure, May:120, Sep:86, Oct:B23
environmentally safe lift, Mar:80
Heavy Duty Lift Program Guide, Jul:66
MPAL portable lift, Aug:72
Senate Productivity Award, Apr:59
SL9-Smart Lift Interactive CD, Jul:66
Rotor Clip, tool brochure, Dec:61
Roush, new Aurora V8 engine, May:32
RTI Technologies
BR35 on-car lathe, Jun:30
RRC770 Refrigerant Management Center, Mar:85, Apr:65, May:125, Jun:68, Aug:73, Sep:92, Nov:107, Dec:64
RVIA *See* Recreational Vehicle Industry Association (RVIA)
RX-7 (Mazda), rough idle/no start ('89-'90), Mar:67-68

S

S4 (Audi), groaning noise when turning left ('92-'94), May:116
S/T-Series truck (GM)
2.2/2.5/2.8-liter, clutch squeak ('84-'95), Jun:56
4.3-liter
backfire on acceleration ('94), Nov:92
sustained detonation ('92), Mar:65
Saab, *See also specific models*
aftermarket injector length shorter than OE, Mar:40
clutch removal and replacement tool, Jun:38
Sable (Mercury)
3.0-liter

broken main cap bolts ('87-'88), May:115-116
intermittent MIL and false DTC ('90), Feb:52
no crank ('92-'95), May:112
transaxle damage ('94-'95), Mar:65
3.8-liter, no crank ('92-'95), May:112
ABS lamp on, DTC stored in memory ('96), Sep:1
brake roughness ('86-'95), Aug:65-66
brake vibration during stop ('86-'93), Jan:1
lack of power/hesitation/stalling with hard restart ('93-'94), Dec:50
new rear camber adjustment kit ('86-'95), Feb:48
nonfunctional blower cover motor ('93-'94), Aug:61-62
Safari (GMC)
4.3-liter, bad fuel pump relay ('93-'94), Jan:48
tough front end alignment, Jan:46
Safety Inspections
inspection form, May:98-99
required vs. suggested repairs, May:100
a service and sales tool, May:97-100
Safety-Kleen, new collection program for used oil filters and waste gasoline, Feb:59, Sep:86
Sales
at the write-up, Jan:22-23
attracting repeat customers, Mar:51-54
the basics of selling service and repairs, Jan:33-36
by service interval, Jan:23
direct mail, Jan:24, 26
discounts and credit, Jan:34, 36
free second opinions, Feb:18-19
safety inspections as a service and sales tool, May:97-100
of services computerized, Jan:22-24, 26
six techniques to promote, Mar:52-54
used-car, Jan:28-29
Samurai (Suzuki), inoperative fuel and temperature gauges ('89-'90), Aug:64
Saturn
ECU software glitch ('92), Oct:22
front brake grind/howl ('91-'95), Jan:47-48
Onboard Refueling Vapor Recovery (ORVR), draining the fuel tank, Sep:50-51
stumble on acceleration ('91-'92), Mar:70
SC (Lexus), 1998 tech report, Dec:23, 26
SCAQMD. *See* South Coast Air Quality Management District (SCAQMD)
Schley Products, high-tech hose clamp pliers, Feb:60
Sebring (Chrysler)
2.0-liter, engine miss ('95), May:113
2.5-liter, intermittent no-start and MIL on ('95), Jul:60
convertible, rear brake chirp ('96), Jun:1
Sentra (Nissan)
ABS Self-Check clunk noise ('91), Jun:1
expanded line of remanufactured transmissions, Jun:64
hesitation and surge ('89), Jan:47
no a/c operation ('93), Apr:58
timing chain replacement ('89), Oct:10, 12-13
Sephia (Kia)
alternator belt squeal ('94-'95), May:116
battery replacement ('94-'95), Oct:32-33
Service Slants, *See also* **Brake System Service Slants**
4Runner (Toyota), 2.4-liter, clutch chatter, Jun:61
80 Quattro (Audi), 2.3-liter, engine warning light illuminates ('89), Aug:61
90 (Audi)
groaning noise when turning left ('92-'94), May:116
no blower motor ('93-'94), Nov:97
90/90 Quattro (Audi), 2.3-liter, engine warning light illuminates ('89), Aug:61
100 (Audi)
2.3-liter, rough idle and stall ('90), Feb:50
power loss/hard starting ('89), Oct:35
200 (Audi), power loss/hard starting ('89), Oct:35
200/200 Quattro (Audi), 2.2-liter, hard cold start ('89-'90), Oct:30
240 (Volvo), brake noise, Jun:57-58
240SX (Nissan), transmission slippage (prior to 5/91), Mar:70, 73
300 (Mercedes-Benz)
SD/SE, parasitic key-off drain, May:113-114
SD/SE, pedal pulsation, Oct:35
300ZX (Nissan)
2+2, detonation ('90), Feb:52
belt squeal, oil leak ('90), Jul:65
transmission slippage (prior to 5/91), Mar:70, 73
Turbo, detonation ('90), Feb:52
318i (BMW)
electrical problems ('93), Nov:97
rough idle with MIL lit ('90), Jan:47
323 (Mazda), 3.6-liter, stalls after start when cold ('88-'90), Jan:48
325i (BMW), electrical problems ('93), Nov:97
400SE (Mercedes-Benz)
brake pedal pulsation, Oct:35
parasitic key-off drain, May:113-114
405 (Peugeot)
1.9-liter, coolant leak ('89-'91), Dec:58
DL/S, intermittent stalling ('89), Aug:64
no start ('89), Nov:94
500 (Mercedes-Benz)
SE/SEL, parasitic key-off drain, May:113-114
SEC/SEL, brake pedal pulsation, Oct:35
525 (BMW), rough idle ('93), Dec:57
525i (BMW), corroded fusible link ('90), Oct:30
530 (BMW), rough idle ('93), Dec:57
530i (BMW), loose oil pump cover (March '94), Mar:74
535i (BMW)
1.1/1.3-liter, hard start/weak performance ('89), Feb:50
stability control simulates misfire ('91-'92), Jul:63
540 (BMW), rough idle ('93), Dec:57
600 (Mercedes-Benz)
SEC/SEL brake pedal pulsation, Oct:35
SEC/SEL, parasitic key-off drain, May:113-114
626 (Mazda)
3.6-liter, stalls after start when cold ('88-'90), Jan:48
idle hunting ('89), Aug:62
635CSi (BMW), 1.1/1.3-liter, hard start/weak performance ('89), Feb:50
735i (BMW)
1.1/1.3-liter, hard start/weak performance ('89), Feb:50
stability control simulates misfire ('91-'92), Jul:63
740 (BMW), rough idle ('93), Dec:57
740 (Volvo)
2.3-liter, squeaks and rattles ('89-'90), Dec:58
high a/c system pressure ('89), Oct:28
740i (BMW), loose oil pump cover (March '94), Mar:74
750 (BMW), rough idle ('93), Dec:57
750iL (BMW), stability control simulates misfire ('89-'90), Jul:63
760 (Volvo), 2.3-liter, squeaks and rattles ('89-'90), Dec:58
840i (BMW), loose oil pump cover (March '94), Mar:74
850 (Volvo), hard starting ('92 on), Nov:96-97
850i (BMW)
5.0-liter, notchy shifting ('92), Nov:92-93
stability control simulates misfire ('91-'92), Jul:63
900 (Saab)
air bag light on ('95), Dec:58
false MIL illumination ('90), Jan:46-47
intermittent check engine light flashing ('89), Sep:83
noisy stabilizer bar bushings ('92), Nov:94
too much clutch freeplay ('94), Jun:63
900S (Saab), no start ('89-'92), Aug:64
911 (Porsche)
Carrera 2, tranny noises when cold ('90-'95), Dec:57
Carrera, engine oil leaks ('89), Sep:83
Carrera, loss of power ('89-'90), Aug:64
Carrera, no cruise control, Nov:94
928 (Porsche)
GT/S4, clutch chatter ('87-'93), Jun:63
S4, adaptive memory and relearn ('87), Jan:48
929 (Mazda)
3.6-liter, stalls after start when cold ('88-'90), Jan:48
rough idle/cold stall ('89), Sep:83
940 (Volvo), brake squeal ('92-'95), Dec:57
944 (Porsche), S, adaptive memory and relearn ('87), Jan:48
960 (Volvo)
brake squeal ('92-'95), Dec:57
oily a/c compressor ('93-'94), Apr:57
5000 (Audi), steering groan ('89), Nov:92
9000 (Saab)
air bag light on ('95), Dec:58
false climate control DTCs ('90-'93), Apr:58
false MIL illumination ('90), Jan:46-47
tire rubbing ('92), Mar:70
9000S (Saab), no start ('89-'92), Aug:64
A4 (Audi)
2.8-liter, rear main seal leak ('96), Dec:57
sedan, false DTC P0461/16845 ('96), Apr:55
Acclaim (Plymouth)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.0-liter, rough idle, stall, hesitation ('90), Mar:67
Accord (Honda), no 1-2 upshift ('84-'92), Nov:97
Achieva (Oldsmobile)
2.3-liter, TCC chuggle ('93), Dec:50
longer-life brake pads ('92-'95), Jun:61, Aug:63
rear brake drag ('95), Aug:59
rough running, hesitation ('94), Feb:48
tightly routed engine harness ('94), Feb:48
Aerostar (Ford)
3.0-liter, broken main cap bolts ('87-'88), May:115-116
4.0-liter, rear main seal tool ('90-'94), Jan:48
ignition module connector change ('94 on), Nov:93
Allanté (Cadillac), noisy accessory drive belt ('93), Oct:24, 28
Amigo (Isuzu)
2.3-liter, high idle ('89-'90), Feb:51-52
2.6-liter, hard starting, fuel pump problems ('89-'90), Mar:70
high idle ('89-'91), Jan:47
Aspire (Ford), brake roughness ('94-'95), Aug:65-66
Astro (Chevrolet)
4.3-liter, bad fuel pump relay ('93-'94), Jan:48
tough front end alignment, Jan:46
Audi, w/center takeoff steering racks, improper tie-rod installation, Oct:24
Aurora (Oldsmobile)
4.0-liter, fuel pressure regulator service ('95), May:112
4.0-liter, noisy accessory drive belt ('93-'95), Oct:24, 28
noisy accessory drive belt ('95), Oct:24, 28
Avenger (Dodge)
2.0-liter, engine miss ('95), May:113
2.5-liter, intermittent no-start and MIL on ('95), Jul:60
B4000 (Mazda), exhaust ticking ('95), May:116
Beretta (Chevrolet)
2.2-liter, hesitation/cold stall/rough running ('92-'93), May:115
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
longer-life brake pads ('92-'95), Jun:61, Aug:63
Blazer (Chevrolet), 4.3-liter, bad fuel pump relay ('94), Jan:48
Bonneville (Pontiac)
3800 V6, revised engine torque specs ('92-'94), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('93-'95), Jul:65
starter motor change ('95), Sep:84
Bravada (Oldsmobile)
4.3-liter, bad fuel pump relay ('94), Jan:48
exhaust noise ('92-'93), Oct:28
Bronco (Ford)
4.9-liter, hesitation/surge ('91-'92), Nov:92
5.0/5.8-liter, belt chirping ('87-'88), Jun:62
5.0/5.8-liter, strange electrical symptoms ('92-'95), Mar:73
electrical problems ('94), Nov:97
harsh shifting and codes ('89-'94), Oct:24
C220/C280 (Mercedes-Benz), leaky trunk, Dec:58
C/K-Series truck (GM)
4.3-liter, sustained detonation ('92), Mar:65
5.7-liter, cold sag/hesitation/sulfur smell ('93), May:114
6.5-liter, black smoke after engine work ('94-'95), Mar:68
6.5-liter, stall, poor throttle response ('94), Sep:82
7.4-liter, low power/overheating ('90-'93), Oct:28-29
clutch master cylinder breakage ('88 on), Jul:63
temperature control lever moves by itself ('88-'94), Jul:60
Camaro (Chevrolet)
3.4-liter, driveability reprogramming ('93), Aug:66
3.4-liter, new "Flash" EEPROM to correct numerous driveability symptoms, May:113
5.0-liter, MIL on with DTC22 stored ('91), Apr:58
5.7-liter, chuggle and/or surge at low rpm while accelerating ('93), Mar:67
5.7-liter, MIL on with DTC22 stored ('91), Apr:58
5.7-liter, noisy accessory drive ('93), Oct:31
Capri (Mercury), brake roughness ('82-'86) ('91-'94), Aug:65-66
Caprice (Chevrolet), 5.0/5.7-liter, MIL on with DTC22 stored ('91), Apr:58
Caravan (Dodge)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.0-liter, rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-'93), Aug:59
ABS engages below 10 mph ('96), Aug:61
cracked fuse block ('94), Aug:63
poor heater and/or air conditioner performance ('84-'94), Feb:51
power steering pump snow shield ('91-'95), Jan:47
seat fuse box cover correctly ('96), Jun:56-57
Cavalier (Chevrolet)
2.2-liter, hesitation/cold

1997 Motor Magazine Index

stall/rough running ('92-'93), May:115
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
longer-life brake pads ('92-'95), Jun:61, Aug:63
Chassis Cab (Dodge)
3500 Series dualie, brake drift ('94-'95), Jul:60, 63
diesel, power loss, harsh shifts ('94), May:112-113
Cherokee (Jeep)
2.5/4.0/5.2-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
water damaged radio ('93), Aug:61
Chevrolet, pickup, premature tire and brake wear ('91-'94), Aug:62
Chrysler
2.2/2.5-liter, proper piston/rod assembly ('81-'95), Jan:46
evaporator part numbers by model, Apr:56
foul a/c odor ('92), Apr:55-56
w/center takeoff steering racks, improper tie-rod installation, Oct:24
Cirrus (Chrysler)
gauges freeze up ('95), Nov:92
insufficient a/c output ('95), Jun:58
intermittent electrical glitches ('95), Oct:31
rear suspension changes ('95), Oct:28
slow or no cranking ('95), Dec:57
slow-speed steering shudder ('95), May:115
updated body control modules ('93), Jul:65
Civic (Honda)
1.5-liter, rough idle/shifter locked ('89-'91), Nov:93
brake vibration ('92-'94), May:112
harsh shifting ('94), Mar:73-74
horn randomly blows in cold weather ('90), Feb:51
intermittent starter grind ('89-'90), Jul:63
no 1-2 upshift ('84-'93), Nov:97
Concorde (Chrysler)
3.5-liter, buck and/or miss at cruising speed ('93), Feb:52
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Concours (Cadillac)
4.6-liter, fuel pressure regulator service ('95), May:112
noisy accessory drive belt ('94), Oct:24, 28
Continental (Lincoln)
3.0/3.8-liter, no crank ('92-'94), May:112
brake roughness ('82-'95), Aug:65-66
lack of power/hesitation/stalling with hard restart ('93-'94), Dec:50
nonfunctional blower cover motor ('93-'94), Aug:61-62
Contour (Ford), brake roughness ('95), Aug:65-66
Corolla (Toyota), transmission noise ('89), Dec:58
Corrado (Volkswagen)
hard and no-start, Aug:64
rear tire wear, Jun:61-62
correction to November, 1996 **Service Slants,** Jan:60
Corsica (Chevrolet)
2.2-liter, hesitation/cold stall/rough running ('92-'93), May:115
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
longer-life brake pads ('92-'95), Jun:61, Aug:63
Cougar (Mercury)
3.8-liter, exhaust moan ('92-'95), Jan:47
3.8/4.6-liter, sluggish shifting/stumble ('94), Jun:58, 61
brake roughness ('82-'95), Aug:65-66
ignition module connector change ('94 on), Nov:93
County (Land Rover), driveline vibration ('94-'95), Oct:35
Crown Victoria (Ford)
4.6-liter, rough idle, miss, stumble ('91-'92), Jul:60
brake roughness ('82-'95), Aug:65-66
erratic shifting ('92-'95), Mar:70
ignition module connector change ('94 on), Nov:93
Cutlass (Oldsmobile)
Calais, longer-life brake pads ('91), Jun:61, Aug:63
Supreme, 3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
D21 truck (Nissan), 2.4-liter, transfer case rattle, Jul:64
Daytona (Dodge), 3.0-liter, rough idle, stall, hesitation ('90), Mar:67
DeVille (Cadillac)
4.6-liter, fuel pressure regulator service ('95), May:112
false a/c codes ('88-'89), Apr:57
hesitation on acceleration ('87), Mar:74
Discovery (Land Rover), driveline vibration ('94-'95), Oct:35
DL (Subaru), inoperative heater ('89), Dec:58
Dynasty (Dodge)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.0-liter, rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-1/2-'93), Aug:59
E-250/E350 (Ford), 7.3-liter, lack of power ('95), Aug:59, 61
Eclipse (Mitsubishi), 2.0-liter, misfiring and codes ('95), Jul:64
Econoline (Ford)
4.9-liter, hesitation/surge ('91-'92), Nov:92
5.0/5.8-liter, belt chirping ('87-'88), Jun:62
7.3-liter diesel, no start ('95), Sep:80, 82
harsh shifting and codes ('89-'94), Oct:24
Eighty Eight (Oldsmobile)
3800 V6, revised engine torque specs ('92-'94), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('93-'95), Jul:65
starter motor change ('95), Sep:84
Elantra (Cadillac)
California 1.8-liter, cold-start stalling (prior to 10/13/92), Mar:73
federal 1.8-liter, cold-start stalling (prior to 12/1/92), Mar:73
Eldorado (Cadillac)
4.6-liter, fuel pressure regulator service ('95), May:112
noisy accessory drive belt ('93-'94), Oct:24, 28
ES300 (Lexus), inaccurate fuel gauge readings (prior to 9/27/91), Mar:67
Escort (Ford)
1.8/2.2-liter, hard start/hesitation/rough idle ('91-'92), Oct:29
1.9-liter, buck and/or jerk at highway speed ('86-'90), May:116
1.9-liter, whining timing belt ('94), Jan:46
brake roughness ('82-'95), Aug:65-66
ignition module connector change ('94 on), Nov:93
Everco Temperature Control, back-to-basics approach to power steering diagnosis and service, Sep:78
Excel (Hyundai)
EGR solenoid valve noise ('90), Aug:61
intermittent no-cranks ('89-'92), Sep:80
Explorer (Ford)
4.0-liter, rear main seal tool ('91-'94), Jan:48
cold-startup noise ('92-'93), Dec:57
ignition module connector change ('94 on), Nov:93
F-250 (Ford)
7.3-liter diesel, no start ('95), Sep:80, 82
7.3-liter, lack of power ('94-'95), Aug:59, 61
7.3-liter Super Duty, refrigerant loss ('95), Apr:58
clutch won't disengage ('93-'95), Oct:35
F-350 (Ford)
7.3-liter diesel, no start ('95), Sep:80, 82
7.3-liter, lack of power ('94-'95), Aug:59, 61
clutch won't disengage ('93-'95), Oct:35
Super Duty 7.3-liter, refrigerant loss ('95), Apr:58
F-Series truck (Ford)
4.9-liter, hesitation/surge ('91-'92), Nov:92
5.0/5.8-liter, belt chirping ('87-88), Jun:62
5.0/5.8-liter, strange electrical symptoms ('92-'95), Mar:73
7.3-liter Super Duty, clutch won't disengage ('93-'95), Oct:35
7.3-liter Super Duty, lack of power ('94-'95), Aug:59, 61
binding clutch ('83-'89), Sep:78
electrical problems ('94), Nov:97
harsh shifting and codes ('89-'94), Oct:24
Fel-Pro Inc.
on improper gasket installations, Jan:48
sealing gasketless engine parts, Sep:78
Festiva (Ford)
brake roughness ('88-'93), Aug:65-66
gear clash/hard shifting ('88), Jun:57
Firebird (Pontiac)
3.4-liter, driveability reprogramming ('93), Aug:66
3.4-liter, new "Flash" EEPROM to correct numerous driveability symptoms, May:113
5.7-liter, chuggle and/or surge at low rpm while accelerating ('93), Mar:67
5.7-liter, noisy accessory drive ('93), Oct:31
Fleetwood (Cadillac)
false a/c codes ('88-'89), Apr:57
hesitation on acceleration ('87), Mar:74
Ford, air conditioning O-ring caution, Feb:51
Fox (Volkswagen)
1.8-liter, erratic idle ('89), Nov:96
loud fuel injectors ('91-'93), May:113
G20 (Infiniti)
ABS light on ('91-'93), Oct:30
blue smoke and/or excess oil consumption ('91), Mar:65, 67
hard cold start and rough idle ('91), Feb:50
G20/G30 truck (GM), 7.4-liter, low power/overheating ('90-'93), Oct:28-29
G-Series truck (GM)
4.3-liter, sustained detonation ('92), Mar:65
5.7-liter, cold sag/hesitation/sulfur smell ('93), May:114
Galant (Mitsubishi)
noisy a/c operation ('94-'95), Apr:58
SOHC engine, timing belt noise ('89), Mar:67
General Motors
inoperative MIL testing procedure update, Feb:52
W-car, 3.4-liter DOHC, slight surge during extended deceleration ('91-'93), Apr:57-58
W-car, stall hot or cold ('91-'92), Apr:57-58
w/center takeoff steering racks, improper tie-rod installation, Oct:24
GL (Subaru), inoperative heater ('89), Dec:58
GMC, pickup, premature tire and brake wear ('91-'94), Aug:62
Golf (Volkswagen)
rear tire wear ('93 and older), Jun:61-62
starter won't engage ('89-'90), Aug:62
Grand Am (Pontiac)
2.3-liter, TCC chuggle ('93), Dec:50
longer-life brake pads ('91-'95), Jun:61, Aug:63
rear brake drag ('95), Aug:59
rough running, hesitation ('94), Feb:48
tightly routed engine harness ('94), Feb:48
Grand Cherokee (Jeep)
2.5/4.0-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
5.2-liter, revised viscous fan clutch ('93), Oct:31
5.2-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
Grand Marquis (Mercury)
4.6-liter, rough idle, miss, stumble ('91-'92), Jul:60
brake roughness ('82-'95), Aug:65-66
erratic shifting ('92-'95), Mar:70
ignition module connector change ('94 on), Nov:93
Grand Prix, 3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
Grand Wagoneer (Jeep), 5.2-liter, revised viscous fan clutch ('93), Oct:31
Honda, 1.8-liter, oil in the coolant ('84), Sep:84
Hyundai
DTC11 and poor driveability, Oct:30
hard starting, Dec:58
Imperial (Chrysler), 3.3/3.8-liter, serpentine belt noise ('91-1/2-'93), Aug:59
Impreza (Subaru), no a/c ('93), May:113
Integra (Acura)
GS-R/LS, ABS light on with DTC1 ('94), Oct:32
no upshift ('86-'89), Mar:74
notchy clutch pedal feel ('90), Mar:68
Intrepid (Dodge)
3.5-liter, buck and/or miss at cruising speed ('93), Feb:52
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Isuzu
pickup 2.3-liter, high idle ('89-'91), Feb:51-52
pickup 2.6-liter, hard starting/fuel pump problems ('89-'90), Mar:70
pickup, high idle ('89-'91), Jan:47
J30 (Infiniti)
cell phone interference ('93), Jun:57
climate control blows hot humid air ('93), Apr:55
Jaguar
3.6-liter sedan, engine pinging ('89), Dec:57-58
sedan, EGR problems ('90), Jan:48
sedan, engine run-on ('90), Aug:62
Jetta (Volkswagen)
rear tire wear ('93 and older), Jun:61-62
starter won't engage ('89-'90), Aug:62
Landau (Chrysler), 3.0-liter, cold hesitation, DTC13 ('89), Mar:68
LeBaron (Chrysler), 3.0-liter, rough idle, stall, hesitation ('90), Mar:67
Legacy (Subaru), DTC32 in memory/no symptoms, Jun:62-63
Legend (Acura)
coupe, metallic knock when cold ('91-'92), May:114-115
inaccurate speedometer reading

1997 Motor Magazine Index

('91), Jul:63-64
no upshift ('86-'93), Mar:74
overflowing brake fluid ('89), Sep:80
sedan, metallic knock when cold ('91-'93), May:114-115
LeSabre (Buick)
3800 V6, revised engine torque specs ('92-'95), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('93-'95), Jul:65
starter motor change ('95), Sep:84
Lexus, modified overdrive clutch bearing, May:116
LHS (Chrysler)
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Loyale (Subaru), white smoke while turning right ('90 and older), Aug:62
LS 400 (Lexus)
groaning noise after engine is shut down ('91), Aug:62
popping brakes ('90), Nov:94
Lumina (Chevrolet)
3.8-liter, gradual power loss ('93-'95), Feb:52
3800 V6, revised engine torque specs ('92-'95), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('93-'95), Jul:65
cold-start and backup stalling, ('90-'93), Apr:57-58
fuel tank noise ('90-'95), Mar:73
Lynx (Mercury)
1.9-liter, buck and/or jerk at highway speed ('86-'90), May:116
brake roughness ('82-'87), Aug:65-66
M3 (BMW)
electrical problems ('93), Nov:97
engine run-on/rough idle ('89), Sep:84
M30 (Infiniti), grinding brakes ('90), Nov:93
M/L-Series truck (GM), 4.3-liter, sustained detonation ('92), Mar:65
Mark VII (Lincoln), brake roughness ('84-'92), Aug:65-66
Mark VIII (Lincoln)
brake roughness ('93-'95), Aug:65-66
hard cold start ('93-'95), Nov:96
ignition module connector change ('94 on), Nov:93
Maserati, 3-liter, rough idle, stall, hesitation ('90), Mar:67
Maxima (Nissan), fan runs continuously ('89-'90), Dec:58
Mercedes-Benz
124-chassis, exhaust noise ('90-'91), Aug:64
124-chassis, faulty cruise control ('89-'90), Feb:51
126/201-chassis, faulty cruise control ('89-'90), Feb:51
300-Series, exhaust noise ('90-'91), Aug:64
hard start/noisy timing case, Dec:58
M102/103 engine, ballooned torque converter, Aug:66
oil leaks, Nov:94
Mercur (Mercury)
Scorpio, brake roughness ('88-'89), Aug:65-66
XR4Ti, brake roughness ('85-'88), Aug:65-66
Metro (Geo)
1.0-liter, cylinder head oil restrictor ('89-'95), May:116
1.0-liter, service manual update/checking ECR pressure tranducer ('89-'94), May:114
Mirage LS (Mitsubishi), tire rubbing ('90), Aug:64
Monaco (Dodge)
3.0-liter, no start/no compression ('90-'92), Apr:52, 55
cam plug charge ('88-'92), Sep:78
MPV (Mazda), 3.6-liter, stalls after start when cold ('88-'90), Jan:48
Mustang (Ford)
5.0-liter, tip-in stumble 30 seconds after hot soak ('88), Jul:63
brake roughness ('82-'95), Aug:65-66
ignition module connector change ('94 on), Nov:93
rear disc brake squeak ('94-'95), Oct:31
MX-6 (Mazda), idle hunting ('89), Aug:62
Mystique (Mercury), brake roughness ('95), Aug:65-66
Neon (Dodge/Plymouth)
2.0-liter, engine miss ('95), May:113
2.0-liter, engine miss ('96), Nov:96
brake growl ('95), Feb:48
electrical glitches, Jun:62
engine racing during shifts ('95), Feb:50
front coil spring part numbers and spring tag ID numbers, Mar:65
front suspension noise ('95), Mar:65
loud fuel pump ('95), May:114
poor defogging ('95), Jun:57
New Yorker (Chrysler)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.3/3.8-liter, serpentine belt noise ('91-1/2-'93), Aug:59
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Salon 3.0-liter, rough idle, stall, hesitation ('90), Mar:67
Ninety Eight (Oldsmobile)
3800 V6, revised engine torque specs ('91-'94), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('93-'95), Jul:65
starter motor change ('95), Sep:84
Nissan, truck, transmission slippage (prior to 5/91), Mar:70, 73
Northstar (Cadillac), 4.6-liter, noise accessory drive belt ('93-'95), Oct:24, 28
Park Avenue (Buick)
3800 V6, revised engine torque specs ('91-'94), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
starter motor change ('95), Sep:84
Park Avenue (Chrysler), 3800 V6, service manual update, YES/NO boxes reversed ('93-'95), Jul:65
Paseo (Toyota), erratic a/c operation ('94), Apr:56
Passat (Volkswagen), rear tire wear, Jun:61-62
Pathfinder (Nissan), transmission slippage (prior to 5/91), Mar:70, 73
Porsche, all models, a/c leaks, May:113
Precis (Mitsubishi)
hard shifting ('90), Nov:94
no-start ('90), Feb:50
Prelude (Honda)
battery drain ('89), Jan:48
drift to the right ('92-'93), Dec:57
no 1-2 upshift ('84-'92), Nov:97
Premier (Eagle)
3.0-liter, no start/no compression ('88-'92), Apr:52, 55
cam plug charge ('88-'92), Sep:78
Previa (Toyota), drone with a/c on ('91), Aug:66
Probe (Ford)
1.8-liter, hard start/hesitation/rough idle ('89-'92), Oct:29
2.2-liter, hard start/hesitation/rough idle ('89-'92), Oct:29
2.2-liter turbo, intermittent MIL ('90-'92), Apr:52
2.5-liter, updated connector on replacement EGR valve ('93-'94), Mar:67
brake roughness ('89-'95), Aug:65-66
hard and/or no-start ('93-'94), Aug:63
no start/hard start and Fuel Shutoff Light lit ('93-'94), May:113
Q45 (Infiniti), idle vibration ('90-'91), May:114, Jul:64
R/V-Series truck (GM), 7.4-liter, low power/overheating ('90-'93), Oct:28-29
Ram truck (Dodge)
5.9-liter diesel, too much oil from draft tube ('94-'95), May:116
5.9-liter, low power, rough idle, black smoke ('94-'95), Mar:73
5.9-liter, surge at highway speeds ('94-'95), Jan:48
8.0-liter, delayed gear engagement ('94-'95), Jun:63
8.0-liter, low power, rough idle, black smoke ('94-'95), Mar:73
8.0-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
brake drift ('94-'95), Jul:60, 63
diesel, delayed gear engagement ('94-'95), Jun:63
diesel, power loss, harsh shifts ('94), May:112-113
hard-to-shift transfer case ('94-'95), Nov:94
replacement climate control knobs ('94-'95), Apr:56
right side speakers go out when electrical accessories are used ('94), Oct:31
Range Rover, 4.0-liter, hard starting/erratic fuel gauge ('95 and earlier), Dec:57
Ranger (Ford)
4.0-liter, rear main seal tool ('90-'94), Jan:48
ignition module connector change ('94 on), Nov:93
rolling hot idle/stall ('94), May:114
Regal (Buick)
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
3800 V6, revised engine torque specs ('94-'95), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
Riviera (Buick), 3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
Rodeo (Isuzu)
downshift clunk ('91-'93), May:116
erratic cruise control ('90-'91), Aug:62
RX-7 (Mazda), rough idle/no start ('89-'90), Mar:67-68
S4 (Audi), groaning noise when turning left ('92-'94), May:116
S/T-Series truck (GM)
2.2/2.5/2.8-liter, clutch squeak ('84-'95), Jun:56
4.3-liter, backfire on acceleration ('94), Nov:92
4.3-liter, sustained detonation ('92), Mar:65
Sable (Mercury)
3.0-liter, broken main cap bolts ('87-'88), May:115-116
3.0-liter, intermittent MIL and false DTC ('90), Feb:52
3.0-liter, no crank ('92-'95), May:112
3.0-liter, transaxle damage ('94-'95), Mar:65
3.8-liter, no crank ('92-'95), May:112
brake roughness ('86-'95), Aug:65-66
lack of power/hesitation/stalling with hard restart ('93-'94), Dec:50
new rear camber adjustment kit ('86-'95), Feb:48
nonfunctional blower cover motor ('93-'94), Aug:61-62
Safari (GMC)
4.3-liter, bad fuel pump relay ('93-'94), Jan:48
tough front end alignment, Jan:46
Samurai (Suzuki), inoperative fuel and temperature gauges ('89-'90), Aug:64
Saturn
front brake grind/howl ('91-'95), Jan:47-48
stumble on acceleration ('91-'92), Mar:70
Scoupe (Hyundai), intermittent no-cranks ('89-'92), Sep:80
Sebring (Chrysler)
2.0-liter, engine miss ('95), May:113
2.5-liter, intermittent no-start and MIL on ('95), Jul:60
Sentra (Nissan)
hesitation and surge ('89), Jan:47
no a/c operation ('93), Apr:58
Sephia (Kia)
alternator belt squeal ('94-'95), May:116
battery replacement ('94-'95), Oct:32-33
Service Slants on disk, Jun:71, Sep:95, Nov:107, Dec:64
Seville (Cadillac)
4.6-liter, fuel pressure regulator service ('95), May:112
noisy accessory drive belt ('93-'94), Oct:24, 28
Shadow (Dodge), False DTC15 ('94), Aug:65
Silhouette (Oldsmobile)
3.8-liter, gradual power loss ('93-'95), Feb:52
3800 V6, revised engine torque specs ('92-'95), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('94-'95), Jul:65
fuel tank noise ('90-'95), Mar:73
Skylark (Buick)
2.3-liter, TCC chuggle ('93), Dec:50
longer-life brake pads ('91-'95), Jun:61, Aug:63
rear brake drag ('95), Aug:59
rough running, hesitation ('94), Feb:48
tightly routed engine harness ('94), Feb:48
Sonata (Hyundai)
2.4-liter, engine stall repair kit ('89-'90), Feb:51
EGR solenoid valve noise ('90), Aug:61
intermittent wiper speed variation ('92-'93), May:116
Spirit (Dodge)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.0-liter, rough idle, stall, hesitation ('90), Mar:67
Stratus (Dodge)
2.0-liter, MIL illuminated/DTC21 ('95), Aug:62
gauges freeze up ('95), Nov:92
insufficient a/c output ('95), Jun:58
intermittent electrical glitches ('95), Oct:31
rear suspension changes ('95), Oct:28
slow or no cranking ('95), Dec:57
slow-speed steering shudder ('95), May:115
updated body control modules ('93), Jul:65
Subaru
hatchback, inoperative heater ('89), Dec:58
L-Series, inoperative heater ('89), Dec:58
L-Series, white smoke while turning right ('90 and older), Aug:62
Sunbird (Pontiac)
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58

1997 Motor Magazine Index

longer-life brake pads ('92-'94), Jun:61, Aug:63
Sundance (Plymouth), False DTC15 ('94), Aug:65
Sunfire (Pontiac)
longer-life brake pads ('92-'94), Aug:63
longer-life brake pads ('95), Jun:61
Super Duty truck (Ford), 7.3-liter diesel, no start ('95), Sep:80, 82
Swift (Suzuki), 1.3-liter, MAP sensor update ('94), May:113
Talon (Eagle), 2.0-liter, engine miss ('95), May:113
Taurus (Ford)
3.0-liter, broken main cap bolts ('87-'88), May:115-116
3.0-liter, intermittent MIL and false DTC ('90), Feb:52
3.0-liter, no crank ('92-'95), May:112
3.0-liter, transaxle damage ('94-'95), Mar:65
3.8-liter, no crank ('92-'95), May:112
brake roughness ('86-'95), Aug:65-66
ignition module connector change ('94 on), Nov:93
lack of power/hesitation/stalling with hard restart ('93-'94), Dec:50
new rear camber adjustment kit ('86-'95), Feb:48
nonfunctional blower cover motor ('93-'94), Aug:61-62
Tempo (Ford)
brake roughness ('84-'94), Aug:65-66
taillight bulb burnout ('92-'94), Sep:84
Tercel (Toyota)
erratic a/c operation ('94), Apr:56
transmission noise ('89), Dec:58
three types of expansion valves, Apr:52
Thunderbird (Ford)
3.0-liter, no crank ('92-'95), May:112
3.8-liter, exhaust moan ('92-'95), Jan:47
3.8-liter, no crank ('92-'95), May:112
3.8/4.6-liter, sluggish shifting/stumble ('94), Jun:58, 61
brake roughness ('82-'95), Aug:65-66
fuel gauge won't read full ('88), Jul:64-65
ignition module connector change ('94 on), Nov:93
Topaz (Ford), brake roughness ('84-'94), Aug:65-66
Topaz (Mercury), taillight bulb burnout ('92-'94), Sep:84
Town Car (Lincoln)
4.6-liter, rough idle, miss, stumble ('91-'92), Jul:60
brake roughness ('82-'95), Aug:65-66
erratic shifting ('92-'95), Mar:70
ignition module connector change ('94 on), Nov:93
Town and Country (Chrysler)
3.0-liter, cold hesitation, DTC13 ('90), Mar:68
3.0-liter, rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-'93), Aug:59
ABS engages below 10 mph ('96), Aug:61
cracked fuse block ('94), Aug:63
poor heater and/or air conditioner performance ('84-'94), Feb:51
power steering pump snow shield ('91-'95), Jan:47
seat fuse box cover correctly ('96), Jun:56-57
Tracer (Mercury)
1.8/2.2-liter, hard start/hesitation/rough idle ('91-'92), Oct:29
1.9-liter, whining timing belt ('94), Jan:46
brake roughness ('87-'89) ('91-'95), Aug:65-66
ignition module connector change ('94 on), Nov:93
Trans Sport (Pontiac)
3.8-liter, gradual power loss ('93-'95), Feb:52
3800 V6, revised engine torque specs ('92-'95), Jun:62
3800 V6, service manual update, Kent-Moore tool not needed ('93), Apr:52
3800 V6, service manual update, YES/NO boxes reversed ('94-'95), Jul:65
fuel tank noise ('90-'95), Mar:73
Trooper II (Isuzu)
2.6-liter, hard starting, fuel pump problems ('89-'90), Mar:70
2.8-liter, intermittent blower ('89), Nov:93-94
downshift clunk ('90-'91), May:116
erratic cruise control ('90-'91), Aug:62
Trooper (Isuzu)
differential chatter ('92-'93), Apr:57
downshift clunk ('92-'93), May:116
false transmission codes ('94), Oct:30
Vigor (Acura)
alarm goes off after unlocking and opening a door ('92-'93), Dec:58
no upshift ('92), Mar:74
Villager (Mercury), blower runs only on high ('93), Apr:56
Vision (Eagle)
3.5-liter, buck and/or miss at cruising speed ('93), Feb:52
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Volkswagen
1.8-liter, poor acceleration, Jul:64
engine codes, Dec:50
w/center takeoff steering racks, improper tie-rod installation, Oct:24
Volvo, 700-Series, radio popping noises, Sep:78, 80
Voyager (Plymouth)
3.0-liter, cold hesitation, DTC13 ('89), Mar:68
3.0-liter, rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-'93), Aug:59
ABS engages below 10 mph ('96), Aug:61
cracked fuse block ('94), Aug:63
poor heater and/or air conditioner performance ('84-'94), Feb:51
power steering pump snow shield ('91-'95), Jan:47
seat fuse box cover correctly ('96), Jun:56-57
Windstar (Ford), 3.0/3.8-liter, no crank ('92-'95), May:112
Wrangler (Jeep)
2.5/4.0/5.2-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
sticky manual windows ('93-'95), Mar:68
XJ6 (Jaguar)
broken valve springs ('90), Sep:82
low oil pressure reading ('95), Mar:73
MIL with DTC12 ('93), Oct:32
XJ12 (Jaguar), low oil pressure reading ('95), Mar:73
XJR (Jaguar), low oil pressure reading ('95), Mar:73
XJS (Jaguar)
MIL with DTC12 ('93), Oct:32
poor EGR operation ('90), Nov:94
XT (Subaru), inoperative heater ('89), Dec:58
Service Technician Education Program (S.T.E.P.), BMW of North America, Aug:67
Service Technicians Society (STS)
1000th member honored, Jan:49
International Congress and Exposition discussion, Apr:2
web site address, Apr:50, May:117, Nov:40
Seville (Cadillac)
4.0-liter, fuel pressure regulator service ('95), May:112
buzz/rattle from instrument panel when brake pedal is depressed ('95-'97), Sep:1
noisy accessory drive belt ('93-'94), Oct:24, 28
Shadow (Dodge), False DTC15 ('94), Aug:65
Shark Industries, brake lathe variable speed gearbox, Sep:34, Oct:B24
Sheffield Research, TA100 SmarTach+, Mar:76
Shop Management
All Pro/Bumper to Bumper, management video series, Oct:B19
Automotive Parts Rebuilders Association (APRA)
Five Ways or More to Make the Best Use of Your Time video, Feb:59
How to Get Customers, Keep Customers and Profit from Endless Referrals video, Feb:59
ISO 9000: The Good, the Bad and the Ugly video, Feb:59
The Internet: How to Market Your Product and Company video, Feb:59
The Secret of Managing and Motivating Today's Demanding Workforce video, Feb:59
Automotive Service Association
Management Institute (ASAMI)
Hiring the Superstars!, Dec:61
Managing Your Business for Profit, Dec:61
S.M.A.R.T. program approved, Jun:64
CARS, *Shop Management Tools for Success*, Jan:53, Feb:65, May:125, Jun:71, Jul:75, Aug:74, Sep:95, Oct:B23, Nov:103, Dec:64
computerized, Jan:22-24, 26
diversification, Jan:27-29
Shure Manufacturing Corp., Tool Toter, Feb:62
Sienna (Toyota)
1998 tech report, Dec:21-22
update ('98), Feb:46
Sierra (GM), update ('97), Feb:45
Significant New Alternatives Program (SNAP), and the EPA, Apr:22-23
Silhouette (Oldsmobile)
3.8-liter, gradual power loss ('93-'95), Feb:52
3800 V6
revised engine torque specs ('92-'95), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52
service manual update, YES/NO boxes reversed ('94-'95), Jul:65
fuel tank noise ('90-'95), Mar:73
new design tie rod end ('93-'95), May:119
update ('97), Feb:45
SK Hand Tool, 75th anniversary tool catalog, Nov:100
Skyhawk (Buick), release bearing/retainer destruction ('87-'89), Jun:32-34
Skylark (Buick)
2.3-liter, TCC chuggle ('93), Dec:50
longer-life brake pads ('91-'95), Jun:61, Aug:63
rear brake drag ('95), Aug:59
rough running, hesitation ('94), Feb:48
tightly routed engine harness ('94), Feb:48
Smithtronics, ST-5300 EGR tester, Mar:85
Smog Check, *See also* Emissions
900 (Saab), SRS light on ('94), Oct:20
2500-Series truck (GMC), 6.2-liter, special scan tool required, Oct:20
Accord (Honda), 2.0-liter, hard and/or no-start ('86), Aug:20-21
Aerostar (Ford), speedometer wavers ('95), Oct:20
Bonneville (Pontiac), poor performance ('89), Feb:19
Cavalier (Chevrolet), 2.0-liter, ASM dyno test ('87), Apr:19, 21
correction to April **Smog Check**, Jun:78
Cutlass (Oldsmobile), Supreme 2.8-liter, intermittent stalling/tuneup, Oct:22
E150 (Ford), replacing the ABS HCU ('94), Oct:20
E320 (Mercedes-Benz)
no oxygen sensor data ('95), Oct:20
special impulse counter scan tool ('94), Oct:20
free-flow mufflers, Jun:18, 20
the future of the auto repair industry, Dec:14-15
"lazy oxygen sensor," Jun:18, 20
loaded-mode emissions testing, Apr:18-19, 21
Mechanics' Education Association (MEA), collecting proprietary information, Oct:20, 22
readers' complaints regarding February column, Apr:65
Saturn, ECU software glitch ('92), Oct:22
Sue Hannibal's last column, Dec:14-15
Taurus (Ford)
3.0-liter, failed smog test ('87), Feb:18
3.0-liter, no power ('87), Feb:18-19
value of free second opinions, Feb:18-19
SNAP. *See* Significant New Alternatives Program (SNAP)
Snap-on Tools
1996 Domestic Combination Primary Cartridge kit for MT 2500 scanner, May:118
Asian Import Combination Cartridge Kit, Feb:60
CDR20 cordless driver/drill, Sep:88
customer confidence survey results, Jan:43
EEAC300A refrigerant identifier, Apr:60
named premier home-based franchise, Dec:61
new training and retail center opens, Jul:58
PT210 air powered right angle die grinder, Nov:98
Tribute campaign, Apr:47
Vantage graphing DMM and Diagnostic Database, Jan:53, Mar:85, May:120, Jul:70, Sep:92, Oct:B24, Nov:103, Dec:63
work shoes and boots, Dec:62
Society of Automotive Engineers (SAE)
Automotive Air-Conditioning Refrigerant Service Guide, May:117, 120
International Congress and Exposition, Apr:2
On-Board Diagnostics for Light and Medium Duty Vehicles Standards Manual, Apr:59
performance standards for electronic leak detectors, Apr:41-42
web site address, Nov:40
Solar
antifreeze recycling machine, Oct:B24, Dec:63
Booster Pac engine starter, Sep:92
Tote-MIG welder, Dec:63
Sonata (Hyundai)
2.4-liter, engine stall repair kit ('89-'90), Feb:51
EGR solenoid valve noise ('90), Aug:61
intermittent wiper speed variation ('92-'93), May:116
South Coast Air Quality Management District (SCAQMD), regulation for water-based cleaning, Mar:60
SP Tools/Schley, *Specialty Hand Tool Catalog*, Jan:53, Mar:80, Apr:65, Jun:68, Jul:70, Sep:82, Oct:B24
Speedway Engine Development, new Aurora V8 engine, May:32
Spirit (Dodge)
3.0-liter
cold hesitation, DTC13 ('89), Mar:68

rough idle, stall, hesitation ('90), Mar:67
SPO. *See* General Motors Service Parts Operations
SPX Corp.
Automotive Diagnostics division, forms network with Mac Tools, Feb:59
strategic alliance with Hewlett-Packard, May:117
SSC (Delco), concept vehicle debut at Automotive Electronics Conference, Jan:14-15
Standard Plus Club, driveability hotline, Mar:36-40, Jun:78
Steel Recycling Institute, Used Oil and Oil Filter Recycling workshops, Jan:44
Stratus (Dodge)
2.0-liter, MIL illuminated/DTC21 ('95), Aug:62
gauges freeze up ('95), Nov:92
grinding or squeaking front brakes ('95-'96), Mar:1
insufficient a/c output ('95), Jun:58
intermittent electrical glitches ('95), Oct:31
rear suspension changes ('95), Oct:28
slow or no cranking ('95), Dec:57
slow-speed steering shudder ('95), May:115
updated body control modules ('95), Jul:65
STS. *See* Service Technicians Society (STS)
Subaru
hatchback, inoperative heater ('89), Dec:58
L-Series
inoperative heater ('89), Dec:58
white smoke while turning right ('90 and older), Aug:62
Sunbird (Pontiac)
3.1-liter, cold-start and backup stalling ('90-'93), Apr:57-58
longer-life brake pads ('92-'94), Jun:61, Aug:63
release bearing/retainer destruction ('87-'89), Jun:32-34
Sundance (Plymouth), False DTC15 ('94), Aug:65
Sunfire (Pontiac), longer-life brake pads ('95), Jun:61, Aug:63
Sure Seal, close quarters wrench, Sep:91
Swift (Suzuki), 1.3-liter, MAP sensor update ('94), May:113
Synergy, Feb:58

T

Talon (Eagle)
2.0-liter, engine miss ('95), May:113
intermittent vibration at highway speed ('90-'91), Dec:6-7
Taurus (Ford)
3.0-liter
broken main cap bolts ('87-'88), May:115-116
failed smog test ('87), Feb:18
intermittent MIL and false DTC ('90), Feb:52
no crank ('92-'95), May:112
no power ('87), Feb:18-19
transaxle damage ('94-'95), Mar:65
3.8-liter, no crank ('92-'95), May:112
ABS lamp on, DTC stored in memory ('96), Sep:1
brake roughness ('86-'95), Aug:65-66
brake vibration during stop (not Police and SHO '86-'93), Jan:1
CCRM schematic, Aug:35
ignition module connector change ('94 on), Nov:93
lack of power/hesitation/stalling with hard restart ('93-'94), Dec:50
new rear camber adjustment kit ('86-'95), Feb:48
nonfunctional blower cover motor ('93-'94), Aug:61-62
Police/SHO, brake vibration ('89-'93), Jan:1
SHO, MTX worn release bearing quill ('89-'94), Jun:34
TCC Sercon, electrically operated refrigerant recovery system, Apr:42
Tech International, Uni-Seal Ultras tire repair seals, Feb:60-61
Technical Chemical Company
Johnson's Freeze 12 alternative refrigerant accepted by EPA SNAP program, Apr:59
Johnson's Ultimate Fuel System Cleaner, Nov:98
Tempo (Ford)
brake roughness ('84-'94), Aug:65-66
MTX worn release bearing quill ('88-'94), Jun:34
taillight bulb burnout ('92-'94), Sep:84
Tenneco Automotive
Ride Expert training clinic, Jul:58
Walker Quiet-Flow mufflers, Feb:59, Oct:B24
Tercel (Toyota)
erratic a/c operation ('94), Apr:56
transmission noise ('89), Dec:58
Texas Instruments
Multi-channel Advanced Remote Control Serial Data Transmitter and Receiver (MARCSTAR), Jan:40
NightDriver thermal imaging system, Jul:59
The Engine Connection, web site address, Dec:61
Thermostats, *It's Not Your Father's Thermostat Anymore,* Dec:36-40, 41, 43
Thexton Mfg., master cylinder bleeder, Sep:90
Thunderbird (Ford)
3.8-liter
exhaust moan ('92-'95), Jan:47
fluctuating temperature, Mar:11, 13-14
no crank ('92-'95), May:112
sluggish shifting/stumble ('94), Jun:58, 61
4.6-liter, sluggish shifting/stumble ('94), Jun:58, 61
brake roughness ('82-'95), Aug:65-66
fuel gauge won't read full ('88), Jul:64-65
ignition module connector change ('94 on), Nov:93
TIF Instruments
corona discharge leak detectors, Apr:41-42
refrigerant identifiers, Apr:40
TIF9010 Electronic Charging Scale, Aug:70
TIF9600D digital manifold gauge, Jul:68
Toledo Trans-Kit, *Import Transmission Application Chart,* Jul:66
Tomco, improved mass airflow sensor, Sep:89-90
Tools and Equipment, *See also* Parts, Accessories and Supplies; **Tools of the Trade**
A Golden Era, tools of the past, Nov:45-47, 50-66, 68-73
Accu-Turn
microprocessor wheel balancer, Nov:103
On-Car Lathe, Jun:68, Dec:64
air conditioner leak detectors, Apr:41-42
ALLDATA, Series 295 technical service bulletin database, Mar:85, Sep:95, Oct:B19
Auto Test System, Scanmaster Pro scanner, May:125
Autodiagnos, ACE information management system, Aug:73, Sep:36, 91, Oct:B20
Automotive Electronics Services, AES Wave! Information Management Software, Sep:40
Automotive Lift Inst., lift point guide, Dec:64
Automotive Test Systems, Model 8700 DIS and KV tester, Dec:63
AutoTool, total transmission service fluid flusher, Sep:40
Benwil Lifts, super duty lift system, Nov:103
Beta Tools
introduced, Aug:73
now available in US, May:120
Bosch replacement Ford IAR alternators, Oct:B20
BWD Automotive, Sure Spark wire sets, Oct:B20
California Auto Tech, Snake-Bit EGR passage cleaner, May:27, Sep:44
CARS, *Shop Management Tools For Success,* Jan:53, May:125, Jun:71, Aug:74, Sep:95, Oct:B23, Nov:103, Dec:64
Champion Pneumatic, Advantage Series compressors, Sep:92, Oct:B20
Clean Burn Inc., used oil furnaces, Oct:B20, Nov:103
Darex, Drill Doctor drill sharpener, Aug:73, Oct:B20
DeltaTRAK, Optex Thermo-Hunter IR-3LF Infrared Thermometer, Sep:38, Dec:63
Edge Diagnostic Systems, Dyno-Tech Diagnostic software, Sep:47-48
Emi-Tech, fuel system analyzer, Sep:38, Oct:B21
ESP, SystemOne emissions inspection system, Oct:B21
Fluke Corp., 98 Series II Auto Scopemeter, Nov:104
flushing equipment, Apr:42, 45-46
Ford Motor Company, *Tools of the Trade Catalog,* Apr:65
Goodall Manufacturing Co., combustion leak tester, Jul:48
H.C. Protek, D688 automotive digital multimeter, Nov:104
Hein-Werner, Blackhawk MultiBench Lift, Nov:104
Hickok Inc., New Generation STAR (NGS) tester, Oct:B21
How to get the Top 20 tools, Sep:48
Identifix, wiring diagrams by fax, Nov:103
Interro Systems
ECVu ECM Analyzer, Sep:36, 38
OBDII scan tool, Oct:B22, Dec:64
John Bean Company
CAS shop management system, Oct:B22
sonic technology wheel balancer, Oct:B22
Visualiner 3D wheel alignment system, Sep:46-47, Oct:B22
K&W Products, Knock'er Loose penetrant, Oct:B22
Kal Equipment, KalScope, Mar:80, May:125, Oct:B22
Kastar Hand Tools
15 piece metric thread restore kit, Nov:104
master power steering pump pulley R/1, May:120
Kent-Moore
black light and trace dye crack detector, Jul:48
GM Mid-year Special Service Tools catalog, Sep:91
Lanair, waste oil heater, Feb:62, Sep:92, Nov:104
Mac Tools Inc.
ET2010 Lab Scope, Sep:44, 46
MacWave diagnostic tool, Oct:B23, Dec:64
MAK Industries, Versapulr Pulling tool, Sep:42
Master Spindle Rethreader die set, Feb:65
Matco Tools, MT1832 3/8" wobble drive air ratchet, Sep:44
Maxwell Dynamometer Systems Inc., emission testing equipment, Mar:80
Midtronics, PowerSensor Micro400 Digital battery analyzer, Sep:42, 44, Oct:B23
Mitchell Repair, CD-ROM transmission repair information, Nov:104
Model 9100 Allsweep Tester, Universal Testing telemarketing scam, May:88-90, 95-96
Model ISS Ignition System Simulator, Universal Testing telemarketing scam, May:88-90, 95-96
Mohawk Resources Ltd.
TP-30 surface mount lift, Sep:88
two post lift comparison booklet, Mar:85, Sep:91, Oct:B23
MOTOR Magazine
back issues, May:125, Jun:71, Aug:73, Sep:95, Nov:107
Service Slants on disk, Jun:71, Sep:95, Nov:107, Dec:64
MPSI
Pro-Link OBDII cartridge, Oct:B23
Spectra-Gas gas analyzer, Nov:104
National Automotive Parts Association (NAPA)
1991-98 Imported New Car Warranty chart, Dec:64
1998 Domestic New Car and Truck Warranties Chart, Sep:95
NIAT subscription program self-study program, Aug:74
OTC
MicroGas 5-Gas Analyzer, Sep:34
Minuteman battery tester, Jan:53
Pro-Cut International, PFM 900 hub-mounted lathe, Jun:30
Raytek, noncontact infrared thermometers, Feb:62, Jul:70, Aug:74, Nov:107, Dec:64
Ready Fixtures, Early Bird key drop box, Feb:62, Jul:70, Nov:107
recovery-only equipment, Apr:42
refrigerant identifier, Mar:40-41
Reznor, used motor oil furnace, Sep:95, Oct:B23, Nov:107, Dec:64
Rotary Lift
2-post surface lift brochure, May:120, Oct:B23
environmentally safe lift, Mar:80
RTI Technologies
BR35 on-car lathe, Jun:30
RRC770 Refrigerant Management Center, Mar:85, Apr:65, May:125, Jun:68, Aug:73, Sep:92, Nov:107, Dec:64
SAE, *Automotive Air-Conditioning Refrigerant Service Guide,* May:120
scanner, a/c-related performance data, Apr:46
Schley Products, adjustable hose clamp pliers set, Sep:40, 42
Shark Industries, brake lathe variable speed gearbox, Sep:34, Oct:B24
Shure Tool Toter, Feb:62
Smithtronics, ST-5300 EGR tester, Mar:85
Snap-on Tools, Vantage Graphing DMM and Diagnostic Database, Jan:53, Mar:85, May:120, Jul:70, Sep:92, Oct:B24, Nov:103, Dec:63
Solar
130 amp cordless portable welder, Nov:103
antifreeze recycling machine, Oct:B24, Dec:63
Booster Pac engine starter, Sep:92
Tote-MIG welder, Dec:63
SP Tools/Schley, specialty hand tool catalog, Mar:80, Apr:65, Jun:68, Jul:70, Sep:82, Oct:B24
SST III Sensor System Tester, Universal Testing telemarketing scam, May:88-90, 95-96
Sure Seal, close quarters wrench, Sep:91
Toyota, *Toyota Star Service News,* Nov:107, Dec:63
Tracer Products
Tracerline Titan blue light leak detectors, Apr:41-42, Oct:B24
Tracerline TP-1800 leak detection lamp, Jun:68
Truecraft Tools
3/8" spline drive multi angle ratchet set, Sep:46
high-piece-count socket set, Jan:53
UView Ultraviolet Systems, Spotgun A/C Dye Injector, Sep:38, 40
Vacutec vacuum leak detector, Sep:38, Oct:B21
vacuum pump accessories, Apr:42
Valvoline, Pyroil super concentrated fuel injector cleaner, Aug:72, Oct:B24
Wynn Oil Company, TranServe II flush and fill machine, Oct:B24
Yokogawa Corp. of America
GA500 Gas Analyzer, Aug:74, Sep:91, Nov:107
H-10PM refrigerant leak detector, Mar:85, Apr:65, May:120, Jun:71, Jul:70

1997 Motor Magazine Index

infrared thermometers, Dec:63
Tools of the Trade, *See also* Parts, Accessories and Supplies; Tools and Equipment
air conditioning
digital electronic refrigerant recharging scale, Jul:68
EEAC300A refrigerant identifier, Apr:60
HeCat FAC 500 Flush 'N' Cycle a/c flushing machine, Jul:68
Model 14780B Sentinel refrigerant identifier, Aug:72
Scavenger Model 17680A a/c recovery system, Apr:60
TIF9010 electronic charging scale, Aug:70
alternators, Iceberg replacement alternator, Aug:68
batteries
Amp Champ 12-volt power supply, Nov:99
BaTap battery tap, Aug:68
Lynx Toolless Terminals, Jun:66-67
MinuteMan portable tester, Apr:61
brakes
Accu-turn Model 7700 combination brake lathe, Feb:61
AMMCO Model 2800 Environmental Lathe Enclosure, Jun:65
brake fluid moisture tester, Jun:66
Brake Force Rotor Gage, Jun:65
brake lathe antichatter aid, Nov:98
DuraStop brake line, Aug:73
Squeak Relief brake finishing treatment, Aug:68
carburetors
Holley float adjusting tool, Aug:70, 72
rebuilding kit, Nov:98
cleaners/washers
Autolife engine cleaning system, Feb:61
Bilstein R-2000 Engine Flush System, Mar:76
diesel injector cleaner, Aug:70
injector cleaning kit, Dec:62
Johnson's Ultimate Fuel System Cleaner, Nov:98
PDX Series portable cold-water pressure washers, Mar:75
Pyroil super concentrated fuel injector cleaner, Aug:72
QD Electronic Cleaner, Mar:76
Spin Jet Automatic Parts Washer, Apr:60-61
custom fender covers, Mar:78
diagnostics
98 Automotive ScopeMeter Series II scope, Apr:62
1996 Domestic Combination Primary Cartridge kit for MT 2500 scanner, May:118
3500 Series timing lights, Dec:62
ADL7100 lab scope, Aug:68
ET18DMM digital multimeter, Jun:67
leak detection lamp, Feb:60
MicroGas gas analyzer, Jul:68
Model 8500A alternator/starter tester, Jun:65
new crank angle sensor, May:119
OBDII Quick Reference Guide, May:118, Dec:62
parasitic drain tester, Aug:70
Qwik-Connect test clips, Feb:61
TA100 SmarTach+ ignition tester, Mar:76
TIF9600D digital manifold gauge, Jul:68
Tracerline TP-1700A ultraviolet leak detection lamp, Apr:59
Tracker UV leak detection system, Aug:69-70
undercar inspection tool, Aug:72
valve seat measuring tools, May:118
drains
AMD-6550 automatic compressed-air drain, Jul:69
Liquid Recovery System, Mar:78
mobile oil drain, Jun:67
Model 3653 antifreeze drain, Aug:68
electrical, Mini-Fusetapper, May:119
engines, Endural Returnable Engine Cases, May:119
filters, Precision Crush PC100 oil filter crusher, Feb:61
Ford
adjustable strut mounts for Mustang ('79-'93), Apr:62
caster/camber adjusting kit for Explorer ('95 on), Mar:78-79
rear cargo springs for Windstar ('95 on), Apr:62
spring lock coupler repair kit, Jul:68
fuel injection
3-in-1 Fuel Injection Service Kit, Mar:76
Ideal 52F Series fuel injection hose clamps, Mar:79
gaskets
Hi-Per Blue performance valve cover gaskets, Nov:99
Problem-Solving head gasket, Jul:69
True-Form oil pan gasket set, Feb:61
General Motors Corp.
various models, new design tie rod ends, ('93-'95), May:119
W-Car, Rear Guide Pin Removal Tool, Feb:61
gloves, latex, Jan:50
PT210 air powered right angle die grinder, Mar:78, Nov:98
hand tools
antenna nut socket set, Feb:61
high-accuracy bore gauges, May:118
high-tech hose clamp pliers, Feb:60
Load-A-Lug Impact sockets, Jun:65
Master spindle rethreader die set, May:119
Model 50750 oil filter pliers, May:118
oil drain plug wrench set, Jan:50
pick set, Mar:75
Snake-Bit flexible EGR passage cleaner drill bit, Jul:69
Tool Kaddy, Jun:66
Truecraft 2000 combination wrenches, Aug:70
wrench selector tool, Aug:72
heaters, Reznor used motor oil heater, Aug:73
lifts and jacks
Banner B67597 high-lift transmission jack, Mar:78
GPI-9 environmentally friendly lift, Dec:62
Model 68 Open Beam general service lift, Jan:50
Model 88 Open Beam general service lift, Jan:50
Model 900 Alignment Lift, Mar:78
Model HR-6 X-Press mobile scissors lift, May:119
MPAL portable lift, Aug:72
new bottle jacks, Jun:65
lubricants and sealants
CatOil compressor/air tool oil, Aug:70
Dr. Tranny's Assemblee Goo, Aug:72
engine sealant kit, Jan:50
SiliKroil penetrant/lubricant, Aug:72
Uni-Seal Ultras tire repair seals, Feb:60-61
mobile work stations, Feb:60
MOTOR Magazine, **Service Slants** on disk, Aug:73
pullers
Master power steering pump/alternator pulley remover/installer kit, Nov:98
Model 43800 Cam-Lock Puller, Mar:76
multipurpose puller set, May:118
puller kit, Jan:50
rear axle service tool, Jun:65
Versapulr pulling tool, Feb:60
shoes and boots, Dec:62
software
AES Wave! lab scope software, Apr:61
Asian Import Combination Cartridge Kit, Feb:60
gas analyzer diagnostic software, Feb:60
spark plug wire set, Mar:76
suspension, Ride Saver Plus reman struts, Nov:99
time clock, Lathem 5000E multifunction, Apr:60
Toyota, improved head gasket, Dec:62
transmissions
flywheel shims, Jan:50
remanufactured, May:119
transmission fluid additive, Aug:70
welders, Millermatic Challenger MIG welder, Jun:66
Top Twenty Tools, Sep:34-48
Topaz (Mercury)
brake roughness ('84-'94), Aug:65-66
MTX worn release bearing quill ('88-'94), Jun:34
taillight bulb burnout ('92-'94), Sep:84
Town Car (Lincoln)
4.6-liter, rough idle, miss, stumble ('91-'92), Jul:60
brake roughness ('82-'95), Aug:65-66
erratic shifting ('92-'95), Mar:70
ignition module connector change ('94 on), Nov:93
Town and Country (Chrysler)
3.0-liter
cold hesitation, DTC13 ('90), Mar:68
rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-'93), Aug:59
ABS engages below 10 mph ('96), May:1, Aug:61
cracked fuse block ('94), Aug:63
poor heater and/or air conditioner performance ('84-'94), Feb:51
power steering pump snow shield ('91-'95), Jan:47
seat fuse box cover correctly ('96), Jun:56-57
update ('97), Feb:40
Toyota, *See also specific models*
3.0-liter, burning excessive oil, Jul:47
throttle position sensors, Mar:22, 24, Apr:14, 17
Toyota Star Service News, Nov:107, Dec:63
truck
3.0-liter, clutch squeal when cold ('90), Jun:36, 38
may not start in wet weather ('90 on), Jul:22, 25
piston slap ('87), Oct:6
vane airflow sensors, Nov:22, 24, 27, Dec:16, 19
Toyota Motor Sales USA, first Toyota Customer Service Center opens, Aug:50
Tracer (Mercury)
1.8/2.2-liter, hard start/hesitation/rough idle ('91-'92), Oct:29
1.9-liter, whining timing belt ('94), Jan:46
brake roughness ('87-'89) ('91-'95), Aug:65-66
front caliper knock during moderate braking ('91-'96), May:1
ignition module connector change ('94 on), Nov:93
Tracer Products
Tracerline Fluoro-Lite/P leak-detection dye meets standards, Jun:64
Tracerline Titan blue light leak detectors, Apr:41-42, Oct:B24
Tracerline TP-1700A ultraviolet leak detection lamp, Apr:59
Tracerline TP-1800 leak detection lamp, Jun:68
UV-Fluorescent dye and detection equipment brochure, Oct:36
Trade Secrets
6000 (Pontiac), LE, heater problem ('91), Jan:12-13
Acura, 3.5RL, Global Positioning System (GPS), Aug:14-15
Camry (Toyota), inoperative air conditioning ('88), Sep:16, 18-19
Chevrolet truck, knocking noise in engine, Apr:8, 10, 12
E350 van (Ford), fading brake pedal ('93), Jun:14, 16-17
free diagnosis trouble, Nov:14, 16, 19
Grand Marquis (Mercury), 4.6-liter, MIL blinking/DTCP1408 in memory ('94), Dec:10, 12-13
Jimmy (GMC), 4.3-liter, natural gas conversion, engine replacement, May:14, 16, 19
keeping things in perspective, Mar:11, 13-14
learning from others, Jun:14, 16-17
making sure customers understand limits, Sep:16, 18-19
meeting challenges, May:14, 16, 19
overbooking, Dec:10, 12-13
practicing "defensive estimating," Oct:10, 12-13
Sentra (Nissan), timing chain replacement ('89), Oct:10, 12-13
son or daughter in family business, Feb:12, 14, 16, 65
Thunderbird (Ford), 3.8-liter, fluctuating temperature, Mar:11, 13-14
tough diagnostic challenges, Jan:10, 12-13
warranty repairs, Apr:8, 10, 12
when it's wise to turn business away, Jul:14, 18-19
working out tension-creating problems, Aug:12, 14-15
Training
automotive scholarship for high school graduates, May:117
Automotive Service Association Management Institute (ASAMI), *Managing Your Business for Profit*, Dec:61
Continuing Automotive Service Education (CASE), Feb:4
Coordinating Committee for Automotive Repair (CCAR), automotive education program study results, Jun:52
Equipment and Tool Institute (ETI), *1997 Member Training Directory*, Nov:100
for the future, Jan:38-39
Moog Automotive, World Training Center, Oct:36
Rotary Lift, SL9-Smart Lift Interactive CD, Jul:66
School-to-Work Educational Resource Guide, May:117
Used Oil and Oil Filter Recycling workshops, Jan:44
Training Programs
Automotive Service Association Management Institute (ASAMI)
Hiring the Superstars! self study course, Dec:61
S.M.A.R.T. program approved, Jun:64
BMW of North America, Service Technician Education Program (S.T.E.P.), Aug:67
Coordinating Committee for Automotive Repair (CCAR), Interactive Satellite Career Fair, Jul:56, 58
EV1, technician training program, Mar:56-58
NAPA Institute of Automotive Technology (NIAT)
Subscription Program self-study technical training, Jun:68
Understanding Automotive Electrical/Electronics self-study program, Feb:59
National Automotive Technicians Education Foundation (NATEF), *Alternative Fuels Vehicle Technician* training video, Oct:36
Overseas Automotive Council (OAC), scholarship programs, Oct:36
Trans Sport (Pontiac)
3.8-liter, gradual power loss ('93-'95), Feb:52
3800 V6
revised engine torque specs ('92-'95), Jun:62
service manual update, Kent-Moore tool not needed ('93), Apr:52

service manual update, YES/NO boxes reversed ('94-'95), Jul:65
fuel tank noise ('90-'95), Mar:73
new design tie rod end ('93-'95), May:119
update ('97), Feb:45
Transmission Rebuilders Network International, Nov:40
Transportation Research Board (TRB), Intelligent Transportation System (ITS), smart roads campaign, Mar:64
TRB. *See* Transportation Research Board (TRB)
Trooper II (Isuzu)
2.6-liter
hard starting, fuel pump problems ('89-'90), Mar:70
intermittent blower ('89), Nov:93-94
2.8-liter, intermittent blower ('89), Nov:93-94
downshift clunk ('90-'91), May:116
erratic cruise control ('90-'91), Aug:62
Trooper (Isuzu)
differential chatter ('92-'93), Apr:57
downshift clunk ('92-'93), May:116
Trouble Shooter
3500HD (GM)
7.4-liter, nonfunctional speedometer and RWAL brake malfunction, Jun:9, 12
7.4-liter, stuck in second gear, Jun:9, 12
Acclaim (Plymouth), 2.5-liter, rough idle/oily sludge-type deposits in throttle body/blade ('93), Mar:6, 8
Accord (Honda), 1.8-liter, smoke on startup ('95), Sep:6, 11-12
Bonneville (Pontiac), 3.8-liter, erratic misfire at 45 to 60 mph ('93), Feb:6, 8, 65
Buick
3.8-liter, intermittent misfire ('93), Jul:6, 10, 12
3800 V6, testing for ignition coil breakdown, Oct:6
Ford
PIP and SPOUT signals, Jan:6-7
PIP and SPOUT signals, magnetic solution, Apr:4, 6
GM, tips for scoping out of the way electronic components, Aug:6, 8
Oldsmobile
307-cubic inch V8, mysterious smog test failures (mid-80s), Nov:10, 12-13
307-cubic inch V8, smog test failure at 2500 rpm ('83-'84), May:6, 10
Talon (Eagle), intermittent vibration at highway speed ('90-'91), Dec:6-7
Toyota, pickup, piston slap ('87), Oct:6
Truecraft Tools
3/8" spline drive multi angle ratchet set, Sep:46
high-piece-count socket set, Jan:53
ProMate Tools catalog revised, Dec:61
Truecraft 2000 combination wrenches, Aug:70
TRW, electronic suspension system, Jan:15
Turbo City, web site address, Mar:75
Two Cents Worth
$895 tuneup, Aug:86, Nov:114
aftermarket jobbers vs. dealerships, May:132, Jul:82
Allsweep 9100/Universal Test Equipment scam, Nov:114
automotive repair decision survey results, Jan:60
compliment
for Bob Cerullo, Sep:102
for Dan Marinucci, May:132, Nov:114
correction
Inside Team ASE Racing in May, 1997 MOTOR, Jul:82
Real-World OBD II in February, 1997 MOTOR, Mar:92
Service Slants in November, 1996 MOTOR, Jan:60
Smog Check in April, 1997 MOTOR, Jun:78
Diagnostic Strategies for Computer Controlled Vehicles, Aug:86
driveability hotline revisited, Jun:78
EASE Simulation Inc., Top 20 Tools award, Mar:92
finding good help, Aug:86
importance of technical training, Jun:78
missed opportunities, Jun:78
MOTOR web site index, Jan:60
observations on association membership, "girlie" calendars and automotive fraud, Feb:72
Product Research, Universal Testing Equipment/Global Test Systems fraud, Jul:82
readers' complaints regarding February **Smog Check,** Apr:65
recognizing competency, Oct:B48
regulatory licensing of auto technicians, Oct:B48
return on training investment, Jul:82
shortage of qualified techs, Dec:74
taking things seriously, Mar:92
tech disputes *Consumer Reports* findings, Mar:92
technician vs. mechanic, May:132, Sep:102, Nov:114
Universal Testing Equipment, scam, Jan:60, Feb:72, Sep:102
where do I go from here, Dec:74
women in automotive business, May:132

U

U-Haul International, brochure on business opportunities, Feb:62
UEI, ADL7100 lab scope, Aug:68
ULEC. *See* Ultra Low Emissions Vehicle (ULEV)
Ullman, pick set, Mar:75
Ultra Low Emissions Vehicle (ULEV), introduced by Mercedes-Benz, May:110-111
Universal Propulsion Co., inflatable seatbelts, Sep:72
Universal Testing Equipment
fraudulent use of MOTOR Magazine name, May:89-90
telemarketing scam, Jan:60, Feb:72, May:88-90, 95-96, Jul:82, Nov:114
UOMA. *See* Used Oil Management Association (UOMA)
URL. *See* World Wide Web (WWW), web site address
Used Oil Management Association (UOMA), name change, Jun:64
UView Ultraviolet Systems, Spotgun A/C Dye Injector, Sep:38, 40
UVP, B-100EP leak detection lamp, Feb:60

V

Valvoline, Pyroil super concentrated fuel injector cleaner, Aug:72, Oct:B24
Valvoline Instant Oil Change
named top oil change franchise, Apr:59
opening in Sears, May:117
Van Norman, V22 combination brake lathe, Sep:88
Venture (GM), update ('97), Feb:45
Vetronix Corp., Mastertech software update for Toyota and Honda, Dec:19
Victor Reinz, *Performance Gasket* catalog, Jun:64
Vigor (Acura)
alarm goes off after unlocking and opening a door ('92-'93), Dec:58
no upshift ('92), Mar:74
Villager (Mercury), blower runs only on high ('93), Apr:56
Vision (Eagle)
3.5-liter, buck and/or miss at cruising speed ('93), Feb:52
brakes, ABS light on intermittently ('93), Jan:1
clicking in front end ('93-'95), Sep:82
front brake service recommendations ('93-'95), Jul:63
Volkswagen, *See also specific models*
1.8-liter, poor acceleration, Jul:64
engine codes, Dec:50
w/center takeoff steering racks, improper tie-rod installation, Oct:24
Volvo, *See also specific models*
200-Series, deteriorated wiring insulation ('80 on), Sep:22, 24
700-Series
deteriorated wiring insulation ('80 on), Sep:22, 24
pump relay and crank sensor trouble ('88-'91), Sep:25
radio popping noises, Sep:78, 80
National Technical Hotline number, Jun:64
new models introduced ('98), Jun:52
Pre Owned Volvo Accessory Guide catalog, Feb:59
wet-weather driveability symptoms on dry days, Sep:26
Voyager (Plymouth)
3.0-liter
cold hesitation, DTC13 ('89), Mar:68
rough idle, stall, hesitation ('90), Mar:67
3.3/3.8-liter, serpentine belt noise ('91-93), Aug:59
ABS engages below 10 mph ('96), May:1, Aug:61
cracked fuse block ('94), Aug:63
poor heater and/or air conditioner performance ('84-'94), Feb:51
power steering pump snow shield ('91-'95), Jan:47
seat fuse box cover correctly ('96), Jun:56-57

W

Wagner Brake Products
brake fluid moisture tester, Jun:66
Hotline, Jun:16-17
introduces three new brake parts assortments, Sep:86
Waste Oil Heating Manufacturing Association, name change, Jun:64
Watsco Components, electrically operated refrigerant recovery system, Apr:42
W.D. Adam, Endural Returnable Engine Cases, May:119
WD-40 Co., introduces T.A.L. (Triple Additive Lubricant), Feb:59
Weld-Light Distributing, welding aid, Sep:88
Wells Mfg., *Counter Point* newsletter, Nov:100
Western Hoists, Model HR-6 X-Press mobile scissors lift, May:119
Windstar (Ford)
3.0/3.8-liter, no crank ('92-'95), May:112
brake MIL illuminates immediately after stopping ('95-'96), Mar:1
rear cargo springs ('95 on), Apr:62
update ('97), Feb:45
Wiring Diagrams, tips on mastering, Jul:30-31, 33-34, 36
Wirthco Engineering
BaTap battery tap, Aug:68
Mini-Fusetapper, May:119
World Wide Web (WWW), *See also* Internet
web site address
ALLDATA, Apr:59
Automotive Engine Rebuilders Association (AERA), Nov:39, Dec:61
Automotive Parts Rebuilders Association (APRA), Nov:39
Automotive Service Association (ASA), Sep:86, Nov:39
Automotive Service Industry Association (ASIA), Nov:39
BWD Automotive, Aug:67
California Air Resources Board (CARB), Nov:40
Cardealerjobs.com, Dec:61
CarPoint, Sep:71
CarTech, Nov:100
CCAR-*Green*Link, Nov:40, Dec:61
Clean Burn, Jun:64
Cooper Industries, Mar:75
Cottman Transmission System, May:117
Eaton Corp., Jun:64
Environmental Protection Agency, Nov:40
FEDWORLD, Oct:22, Nov:40
Hannay Reels, Jun:64
Hennessey Industries, Mar:75
ICI Klea, May:117
International Automotive Technicians' Network (iATN), Apr:2, 59, Oct:22, Nov:40
International Franchise Association (IFA), Jan:28
Kastar Hand Tools, Mar:75
Littelfuse Aftermarket Products, Mar:75
Management Information Systems Group, Jun:64, Oct:36
Melling Automotive Products, May:117
Micro Processor Systems Inc. (MPSI), Oct:36
Miller Electric Mfg., Sep:86
Mobile Air Conditioning Society (MACS), Jul:66, Nov:40
Mohawk Lifts, Oct:36
MOTOR Magazine, Jan:60
Motorist Assurance Maintenance Program (MAP), Nov:40
Mr. Gasket, Jul:66
National Institute for Automotive Service Excellence (ASE), Apr:59, Nov:39
Parts Plus, Sep:86
Raybestos Brakes, Mar:80
Service Technicians Society (STS), Apr:50, May:117, Nov:40
Society of Automotive Engineers, Nov:40
The Engine Connection, Dec:61
Transmission Rebuilders Network International, Nov:40
Turbo City, Mar:75
Wrangler (Jeep)
2.5/4.0/5.2-liter, rough idle, miss and/or hard or no-start ('94-'95), Mar:65
clutch slippage ('94), Jun:34, 35
sticky manual windows ('93-'95), Mar:68
update ('97), Feb:40
WWW. *See* World Wide Web (WWW)
Wynn Oil Company, TranServe II flush and fill machine, Oct:B24

X

XJ6 (Jaguar)
broken valve springs ('90), Sep:82
low oil pressure reading ('95), Mar:73
MIL with DTC12 ('93), Oct:32
XJ12 (Jaguar), low oil pressure reading ('95), Mar:73
XJR (Jaguar), low oil pressure reading ('95), Mar:73
XJS (Jaguar)
MIL with DTC12 ('93), Oct:32
poor EGR operation ('90), Nov:94
premature rear brake pad wear, Mar:1
XT (Subaru), inoperative heater ('89), Dec:58

Y

Yokogawa Corp. of America
GA500 Gas Analyzer, Aug:74, Sep:91, Nov:107
H-10PM refrigerant leak detector, Mar:85, Apr:65, May:120, Jun:71, Jul:70
infrared thermometers, Dec:63